

315 South End Ave
Parking Garage - Gateway
Plaza

15 Air Samples were collected. The Summary
results match my computation (below $\approx 70 \text{ f/nm}^2$).

Air Sampling Results

375 South End Ave.
PARKING GARAGE - GATEWAY PLAZA

Location

Total Samples

Results

1. South West Corner Lower Level (Level 1)	→ 1	→ < 70 F/mm ²
2. North West Corner Lower Level	→ 1	→ < 70 F/mm ²
3. Center (Level-1) Lower Level	→ 1	→ < 70 F/mm ²
4. South East Corner Lower Level	→ 1	→ < 70 F/mm ²
5. North East Corner Lower Level	→ 1	→ < 70 F/mm ²
6. North West Corner 1st Flr Level	→ 1	→ < 70 F/mm ²
7. South West Corner 1st Flr Level	→ 1	→ < 70 F/mm ²
8. Center (Level-2) 1st Floor Level	→ 1	→ < 70 F/mm ²
9. North East Corner 1st Flr Level	→ 1	→ < 70 F/mm ²

Air Sampling Results

375 South End Ave.
Parking Garage - Gateway Plaza

<u>Location</u>	<u>Total Samples</u>	<u>Results</u>
10. South East Corner 1st floor Level	→ 1 →	< 70 F/mm ²
11. South West Corner 2nd floor Level	→ 1 →	< 70 F/mm ²
12. Northwest Corner 2nd floor Level	→ 1 →	< 70 F/mm ²
13. Center (Level-3) 2nd floor Level	→ 1 →	< 70 F/mm ²
14. South East Corner 2nd flr Level	→ 1 →	< 70 F/mm ²
15. North East Corner 2nd flr Level	→ 1 →	< 70 F/mm ²

$E = 15$
Samples.