

DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368
JOEL A. MIELE, SR., P.E.
COMMISSIONER

BULK
ANALYSIS CHAIN OF CUSTODY

Incident No.: _____

Date Sampled: 2/27/02Premise: 395 SOUTH END AVE #600Boro: MANHATTANTime: 12:45 am/pmInspector: R. RAMANOHAN
Print[Signature]
SignatureTurnaround Time: Immediate ☒ 24 Hours ☐ 48 Hours ☐ 1 Week ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20227/A078006	Sand & mud	Roof East wing	
2. 20227/A078007	Sand & mud	Roof West wing	
3. 20227/A078008	Sand	Roof North	
4. 20227/A078009	Sand	Roof South	
5. 20227/A078010	Sand	Roof mid section	
6.			
7.			
8.			
9.			
10.			

ANALYSIS REQUESTED: Asbestos PLM ☒Asbestos TEM ☐Lead ☐

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

DEP-ACLP RE-140

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME R-RAMMOHAN BADGE # A078 DATE 02/27/02

LOCATION 395 SOUTH END AVENUE BLDG # 600

ROOF


- ☒ No Visible Debris *GRAVEL WAS REPLACED AFTER 9/11 AS PER SUPER.*
☐ Entire Roof Covered with Debris
☐ Partial Roof Covered
 ☐ Local/Isolated Areas
 ☐ Gutters
 ☐ 25% of the roof
 ☐ 50% of the roof
 ☐ 75% of the roof

FACADE

- ☒ Clean *WAS VACUUMED AND WASHED AS PER SUPER.*
☐ Entire Facade req. Clean-up
☐ _____ Req. Clean-up



 NEW GRAVEL
 SAMPLE LOCATION




* MUD LIKE MATERIAL OBSERVED BELOW GRAVEL

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME R. RAMMOHAN BADGE # A078 DATE 02/27/02
 LOCATION 395 SOUTH END AVENUE BLDG # 600

X GRAVEL WAS REPLACED AFTER 9/11 AS PER SUPER.

X WAS VACUUMED AND WASHED AS PER SUPER.




* MUD LIKE MATERIAL OBSERVED BELOW GRAVEL

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME R. RAMMOHAN BADGE # A078 DATE 02/27/02
LOCATION 395 SOUTH END AVENUE BLDG # 600

X GRAVEL WAS REPLACED AFTER 9/11 AS PER SUPER.

X WAS VACUUMED AND WASHED AS PER SUPER.



X MUD LIKE MATERIAL OBSERVED BELOW GRAVEL