

WTC Visual Survey Form

Premise Address: <u>365 South 4th Ave</u>		
Block: <u>16</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>100</u>	Mix Use ☐ Other ☐	
# of Stories: <u>19</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>Gateway Plaza</u>		FAX: ()
Address:		
On Site Contact:		
Name: <u>De Francisco</u>		Telephone Number: (212) <u>321-2000</u>
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☒ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North ☐ N/A South ☐ N/A East ☐ N/A West ☐ N/A	Inspected ☒ Yes ☐ No		Debris ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
	☒ Yes ☐ No		☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
	☒ Yes ☐ No		☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
	☒ Yes ☐ No		☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Facade Description: <u>Broken windows etc</u>					
Roof					
Debris: ☒ No Visible /Fine Layer <u>Light dust</u> ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: _____					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Comments					

Date: 1/28/2002

Inspection Team: Name: AL

Name: Roc

Agency: SEA?

Agency: SEA?

Page: 1 Document Name: Extra

01/30/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
 MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
 365..... SOUTH END AVENUE..... 1 MANHATTAN 10280 BIN# 1083374
 DCP GEOGRAPHICAL INFORMATION:
 SOUTH END AVENUE 365 - 365 HEALTH AREA : 89 TAX BLK: 16...
 SOUTH END AVENUE 375 - 375 CENSUS TRACT: 19013 TAX LOT: 100..
 SOUTH END AVENUE 385 - 385 COMMUNITY BD: 101 CONDO :
 SOUTH END AVENUE 395 - 397 MULTI STRUCT: 6 CUI NO :
 DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
 OWNER NAME : MARINA TOWERS ASSOC MARINA TOWERS ASSOC
 CORP. NAME : LPC LANDMARK STATUS: NO
 ADDRESS : 9777 QUEENS BLVD DOB LOCAL LAW STATUS: NO
 FLUSHING NY 11374-3317
 DOF BUILDING INFORMATION:
 BLDG SIZE; ** UNKNOWN ** TRANS LAND VALUE: 0
 LOT SIZE: ** UNKNOWN ** TAX EXEMPT FLAG : NO
 BLDG CLASS : D6 ELEVATOR APT TAX EXEMPT CLASS:
 STORIES : 0 CITY OWNERSHIP : NO
 UPDATE DATE : 01/12/02
 FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
 OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

 PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/30/ 2 Time: 08:26:38 AM

WTC Visual Survey Form

Premise Address: <u>365 Southwind Ave</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>19</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>Gateway Plaza</u>		FAX: ()
Address:		
On Site Contact:		
Name: <u>San Francisco</u>		Telephone Number: (<u>212</u>) <u>321-2000</u>
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☒ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☐ No		Locations: _____
Air Monitoring ☒ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	Debris	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Broken windows etc</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ^{Light Dust} ☐ ½ to 1" ^{1 dust} ☐ > 1" ^{1 dust}					
Description: _____					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 1/28/2002Inspection Team: Name: ALName: KevinAgency: SEIAgency: SEI