

385 South End Avenue

7-story, 83 residential units

Roof and Basement Kitchen and Bathroom Exhausts	outside air dampers return air grille return air blower assembly
Ground Floor HV Unit	1 st Floor Fresh Air Supply Duct
Laundry Room HV Unit #21 2 nd Floor Mechanical Room	outside air intake louvers, grates, and/or screens outside air duct outside air dampers return air grilles return air plenum return air ducts turning vanes filter rack filter banks/media pre-heat coils acoustic blower housing blower assembly supply air ducts supply duct linings
Compactor Room HV Unit	?

Problem with report with regard to areas identified with WTC debris, the recommended scope of work, and the checklist.