



Warren & Panzer Engineers, P.C.

228 East 45th Street
New York, New York 10017
Tel. (212) 922-0077
Fax (212) 922-0630

July 31, 2002

Mr. Leonard G. Atteloney
New York City Department of Environmental Protection
96-05 Horace Harding Expressway
Corona, NY 11368

Re: **Final Clearance TEM Air Sample Results**

W&P File #: 1079.01.02

Dear Mr. Atteloney:

On July 28, 2002, a roofing-cleaning project was completed at the building located at 50 Broadway. Transmission Electron Microscopy air samples were collected at the completion of the abatement work. Final clearance air samples collected met the clearance criteria of less than 70 Structures per square millimeter set forth by the NYS Department of Labor Industrial Code Rule 56 and the NYC Department of Environmental Protection Title 15, Chapter 1 Asbestos Rules and Regulations, and this area can now be re-occupied.

Along with this correspondence, I have enclosed a copy of the final visual inspection checklist. If you have any questions or should you need additional information, please contact me at (212) 922-0077.

Sincerely,

WARREN & PANZER ENGINEERS, P.C.

Michael R. Nolan
Senior Project Manager

cc: Krish Radhakrishnan, PE
Attachment(s)

*A Member of
The Warren & Panzer Group*

Warren & Panzer Group

FINAL VISUAL INSPECTION OF ABATEMENT PROJECTS

W&P Project #:...1079-01-02.....

Project Name:...DEP ROOFS AND FACADES CLEANING.....

W&P Project Manager:

Abatement Contractor: TRIO.....

Job Location: 50 BROADWAY.....

Type of Abatement: (circle)

Cleaning

Removal

Enclosure

Glovebag

Encapsulation

Visual Inspection checklist (No Residual Dust or Debris Observed Yes or No)

Floor:.....

Parapet walls:.....

Parapet ledges:.....

Bulkheads:.....

Roofs:..... NO

Ventilation Duct:

Miscellaneous Surfaces:

Facades: (WINDOWS)..... NO

Circle One

Pass

Fail

Field Notes: (Record any problems encountered here.)

.....

Name: EDWIN B. ELLIS.....

Signature: Edwin B. Ellis.....

Date: 7/28/02 SUN