

WTC Visual Survey Form

Premise Address: <u>50 BROADWAY</u>		
Block: <u>29</u>	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
Lot: <u>29</u>		
# of Stories: <u>29</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact: <u>Steve Castellano</u>		
Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
		Inspected	Debris
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
Facade Description: <u>broken windows etc</u>			
Roof			
Debris: ☐ No Visible /Fine Layer <u>Light dust</u> ☒ 1/2 to 1" of dust ☐ > 1" of dust.			
Description: <u>in small pockets</u>			
Setbacks ☐ N/A			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Comments			

Date: 5/22/2002

Inspection Team: Name: CARL
Name: _____

Agency: _____
Agency: _____