

WTC Visual Survey Form

Premise Address: 55 Broadway

Block: Residential ☐ Commercial ☐ Name of Building: 1 Exchange Plaza
 Lot: Mix Use ☐ Other ☐

of Stories: 10 AKA's: Property
 Building Owner/Management: Domini Plano Telephone Number: (212) 344 3450
 Name: Domini Plano (Cohen) FAX: ()
 Address:

On Site Contact: Domini Plano Engineer
 Name: Domini Plano Telephone Number: ()

Building Owner Management Activities
 Interior Survey Performed ☒ Yes ☐ No
 Exterior Survey Performed ☒ Yes ☐ No
 General Clean Up ☐ Yes ☒ No Locations: All samples negative
 ACM Clean Up ☐ Yes ☒ No Locations:
 Air Monitoring ☒ Yes ☐ No Locations:

Copies of All Reports and Data Requested ☒ Yes

Visual Inspection Results:

Facade:

	Inspected	Debris
North	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Facade Description: Basement windows etc. Windows were worked

Roof

Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"

Description: Roof layers with gravel

Setbacks N/A ☐

Floor:	Debris:
Floor: <u></u>	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: <u></u>	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: <u></u>	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: <u></u>	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: <u></u>	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Comments: Fans shut down immediately. Bldg was
an. light
roof

Date: 1/24/2002

Inspection Team: Name: Carla Hirschman Agency: DEM
 Name: Agency:

ENTERED

18

WTC Visual Survey Form

Premise Address: <u>55 Broadway</u>		
Block:	Residential ☐ Commercial ☐	Name of Building: <u>1 Exchange Plaza</u>
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's: <u>Property</u>	
Building Owner/Management:		Telephone Number: <u>(212) 344 3450</u>
Name: <u>Domino Blanco (Cohen)</u>		FAX: <u>()</u>
Address:		
On Site Contact:		
Name: <u>Domino Blanco Engineer</u>		Telephone Number: <u>()</u>
Building Owner Management Activities		
Interior Survey Performed ☒ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☐ Yes ☒ No	Locations: <u>All samples negative</u>	
ACM Clean Up ☐ Yes ☒ No	Locations:	
Air Monitoring ☒ Yes ☐ No	Locations:	
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>main windows etc. Windows were washed</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: <u>Roof layers with gravel</u>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Comments <u>Fans shut down immediately. Bldg was</u>					
<u>air tight</u>					
<u>roof</u>					

Date: 1/24/2002
 Inspection Team: Name: Carla Hutchinson Agency: DEM
 Name: _____ Agency: _____