

WTC Visual Survey Form

1000817

25 Beaver St
 Premise Address: 15, 25 & 33 ~~60~~ STREET aka 60 Broad Street
 Block: 24 Residential ☐ Commercial ☒ Name of Building:
 Lot: 1 Mix Use ☐ Other ☐
 # of Stories: 40 AKA's:
 Building Owner/Management: CRG, mgmt, LLC Telephone Number: (212) 483-8890.
 Name: Teresa J. McGovern FAX: ()
 Address: 60 BROAD STREET, NY NY 10004
 On Site Contact: Sal, Engr.
 Name: Teresa, Bldg Manager Telephone Number: ()
 Building Owner Management Activities
 Interior Survey Performed ☐ Yes ☐ No
 Exterior Survey Performed ☐ Yes ☐ No
 General Clean Up ☒ Yes ☐ No Locations: _____
 ACM Clean Up ☐ Yes ☐ No Locations: _____
 Air Monitoring ☒ Yes ☐ No Locations: _____
 Copies of All Reports and Data Requested ☒ Yes

Visual Inspection Results:

Facade:
 North ☐ N/A Inspected ☒ Yes ☐ No Debris ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 South ☐ N/A ☒ Yes ☐ No ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 East ☐ N/A ☒ Yes ☐ No ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 West ☐ N/A ☒ Yes ☐ No ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Facade Description: _____

 Roof
 Debris: ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Description: _____

 Setbacks N/A ☐
 Floor: 27 Debris: ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Floor: 19 Debris: ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Floor: 11 mixed with granite Debris: ☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
 Floor: Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Floor: 15 Debris: ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
 Comments
 Teresa called our office on 2/25/02 and I advised her to sample the debris and she agreed.

Date: 2/21/2002

Inspection Team: Name: RAMMOHAN
 Name: _____Agency: DEP
 Agency: _____

WTC Visual Survey Form

Premise Address: <u>60 Broad St</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
	Inspected	Debris	
North	☐ N/A ☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South	☐ N/A ☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A ☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A ☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description:			

Roof			
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"			
Description: _____			

Setbacks ☐ N/A			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments			
<u>NO ACCESS. (ONLY ON WEEKDAYS) AS PER SECURITY GUARD</u>			

Date: 3/23/2002
 Inspection Team: Name: RAMMOHAN Agency: DEP
 Name: _____ Agency: _____