

WTC Visual Survey Form

1000820

Premise Address:

50 Broadway street

Block: 24

Residential ☐Commercial ☒

Name of Building:

Lot: 36

Mix Use ☐Other ☐

of Stories: 20

AKA's:

Building Owner/Management: Cushman & Wakefield Telephone Number: (212) 425-1058

Name: Mark Ferguson

FAX: ()

Address: 88 pine street

On Site Contact: ~~Seamus~~ porter

Name: Frank Beck

Telephone Number: ()

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ NoExterior Survey Performed ☐ Yes ☐ NoGeneral Clean Up ☒ Yes ☐ No Locations: _____ACM Clean Up ☐ Yes ☐ No Locations: _____Air Monitoring ☒ Yes ☐ No Locations: _____Copies of All Reports and Data Requested ☒ Yes

Visual Inspection Results:

Facade:

North ☐ N/ASouth ☐ N/AEast ☐ N/AWest ☐ N/A

Inspected

☒ Yes ☐ No☒ Yes ☐ No☒ Yes ☐ No☒ Yes ☐ No

Debris

☒ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"☒ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"☒ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"☒ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Facade Description:

new street side windows sills, all sides, & ledges

Roof

on roof of cooling tower

Debris: ☒ No Visible /Fine Layer☒ 1/2 to 1"☐ > 1"

Description: on roof also debris observed.

Setbacks N/A ☒

Floor: _____

Debris: ☐ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer☐ 1/2 to 1"☐ > 1"

Comments

Date: 2/22/2002

Inspection Team: Name: RAMMOHAN

Agency: NYC DEP.

Name: _____ Agency: _____