1000322

WTC Visual Survey Form

Premise Address: 43-47 BROAD ST.

Block: 23 **Lot:** 78	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐ _____	**Name of Building:**
# of Stories: 8	**AKA's:**	

Building Owner/Management: Telephone Number: ( )
Name: FAX: ( )
Address:

On Site Contact:
Name: Telephone Number: ( )

Building Owner Management Activities
NO INFO. AVAIL. NO ACCESS.

Interior Survey Performed ☐ Yes ☐ No
Exterior Survey Performed ☐ Yes ☐ No
General Clean Up ☐ Yes ☐ No Locations: _____
ACM Clean Up ☐ Yes ☐ No Locations: _____
Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"

Facade Description:
WINDOWS, LEDGES & ORNAMENTATION HAS THICK LAYER OF DUST

Roof

Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"
Description: ENTIRE - ALSO WATER COLLECTED LAYER ON ENTIRE ROOF INCL. UPPER ROOFS - TANK W/ COVER FALLING APART - FLAGPOLE. INSPECTED FROM 55 BROAD ST.

Setbacks N/A ☒

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 2/17/2002 Inspection by: Name: Renay Theodorellys Agency: NYCOEP
Name: _____ Agency: _____