

WTC Visual Survey Form

1001279

Premise Address: <u>25 Beekman Street</u>		
Block: <u>92</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>34</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>Wolf Raymond Et Al</u>		FAX: ()
Address: <u>c/o Rapid Park Industries 204 W 101st NY 10025</u>		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed	☐ Yes ☐ No	<u>Cleaned 5x top to bottom according to Attendant</u>
Exterior Survey Performed	☐ Yes ☐ No	
General Clean Up	☐ Yes ☐ No	
ACM Clean Up	☐ Yes ☐ No	
Air Monitoring	☐ Yes ☐ No	
Locations:		
Locations:		
Locations:		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:**Facade:**

North ☐ N/A
 South ☐ N/A
 East ☐ N/A
 West ☐ N/A

Inspected

☐ Yes ☐ No
☐ Yes ☐ No
☐ Yes ☐ No
☐ Yes ☐ No

Debris

☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"

Facade Description:

RoofDebris: ☐ No Visible /Fine LayerDescription: couple of large heaps of WTC debris on the roofSetbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

CommentsParking Garage.Date: 2/15/2002Inspection by: Name: C.L.Agency: DEP

Asbestos Inspection Report

Premise No. 25 BEEKMAN STREET					Inspection Date: AS NOTED	
Floor ROOF	Zip	Borough 1	Block 92	Lot 34	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type PARKING GARAGE		Basis of Inspection WTC Survey		Photos Taken Yes/No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		

THURSDAY JUNE 13 2002

WORK BEGINS ON THE REAR FIRE ESCAPES OF THE PARKING GARAGE. A REMOTE DECON UNIT HAS BEEN ERECTED ONE LEVEL BELOW THE ROOF WORK AREA. AIR MONITORING IS BEING PERFORMED BY LUIS SOTO (CERTIFICATE # AH 00-20894 EXP 03/03) OF WARREN & PANZER ENGINEERS

FRIDAY JUNE 14 2002

WORKERS BEGIN THE CLEANING OF THE MECHANICAL (ELEVATOR) ROOM STAIR CASES AT 9:00AM. WORK ALSO COMMENCES ON THE ROOF OF THE GARAGE. AIR MONITORING (SAMPLING) IS BEING PERFORMED BY LUIS SOTO OF WARREN & PANZER ENGINEERS. STAIR CASE CLEAN-UPS ARE COMPLETED AT 1:00 PM. THE ROOF WORK AREA HAS BEEN COMPLETED AT 5:30 PM. I CONDUCT A VISUAL INSPECTION OF THE WORK AREAS AND FIND THAT ALL WORK AREAS CLEANED ARE FREE OF VISIBLE WTC DEBRIS. THE PROJECT IS NOW COMPLETE.