

WTC Visual Survey Form

Premise Address: 69 GOLD STREET		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description:					
TERRACES DIRTY					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description:					
GRAVEL ROOF					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
No Exterior Cleaning was done.					

Date: 2 / 15 /2002Inspection by: Name: C.LAgency: _____
Agency: _____



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

*No Exterior
cleaning
done
Terraces
dirty also*

February 15, 2002

Building Owner Name: NYU Downtown Hq

Address: 170 W 8th St

Subject: 69 Gold St

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above-referenced site, visible dust accumulations were observed at:

- ☒ building facade(s)
- ☐ setback(s)
- ☒ roof - gravel roof
- ☐ other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by February 27, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
R. Radhakrishnan, P.E.
Director
Asbestos Control Program





The City of New York
Department of Environmental Protection

59-17 Junction Boulevard
 Corona, New York
 11368-5107

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner
Bureau of Environmental Compliance
 Tel (718) 595-4418
 Fax (718) 595-4422

February 15, 2002

Building Owner Name: NYU Downtown

Address: 170 W 4th St
NY NY

Subject: 69 Gold St

Dear Sir/ Madam:


In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,


R. Radhakrishnan, P.E.
Director
Asbestos Control Program



(718) DEP-HELP

Page: 1 Document Name: Extra

GEO BIN HAS BEEN CHANGED---USE OTHER BINS THEN HIT PF6
03/01/02 PUBLIC ACCESS PROPERTY PROFILE OVERVIEW BISPIQ70
16..... BEEKMAN STREET..... 1 MANHATTAN 10038 BIN# 1000000

NYU DOWNTOWN HOSPITAL NO NUMBER - HEALTH AREA : 77 TAX BLK: 100..
BEEKMAN STREET 40 - 60 CENSUS TRACT: 1501 TAX LOT: 1....
SPRUCE STREET 26 - 42 COMMUNITY BD: 101 CONDO :
WILLIAM STREET 170 - 170 MULTI STRUCT: 02 VACANT :
=====

DOB SPECIAL PLACE NAME : 0 PROPERTY RECORD(S)

DOB BUILDING REMARKS :

FINANCE OCCUPANCY CODE : LANDMARK STATUS:

OTHER BINS : 1001352

COUNTS FOR THIS BIN

ACTIONS	: 2345	, 0	JOBS/FILINGS (PF4)	RECORD VERIFIED :
VIOLATIONS DOB	: 628	, 263	OPEN	SPECIAL STATUS :
ECB	: 116	, 31	OPEN (PF12)	LOCAL LAW :
COMPLAINTS	: 4	, 3	OPEN (PF11)	SRO :

PF 3 = ELEVATORS	ENTER KEY= ACTIONS	PF 5/6/7 = NEW ADDR/BIN/BLK-LOT
PF 8 = BOILERS	(TYPE :)	PF 9/10 = BROWSE BIN/BLK-LOT
*NO ARA'S FILED		PF 15 = BROWSE 0 PROPERTY RECORDS
PF 14 = LPC/HPD/LOFT USE ONLY		PF 16 = ADDTN'L PROPERTY INFO

Date: 3/1/ 2 Time: 05:54:09 PM