

WTC Visual Survey Form

Premise Address: <u>52 BEEKMAN ST</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's: <u>170 WILLIAM ST.</u>	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☐ No		Locations: _____
Air Monitoring ☐ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"
South	☐ N/A		☐ Yes ☐ No		☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East	☐ N/A		☐ Yes ☐ No		☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West	☐ N/A		☐ Yes ☐ No		☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Facade Description: _____					

Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					

Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 2/15/2002Inspection by: Name: C.L.

Name: _____

Agency: NYC DEP

Agency: _____

ASBESTOS INSPECTION REPORT

PAGE 1 OF

PERMISE NO. 52		STREET Beekman St / 170 William Street		INSPECTION DATE 10/10/02	
DOR FACADE	ZIP 10038	BORO CODE 1	BLOCK 100	LOT 1	SQUAD # 1
SPECTOR J. HENSON		BLDG TYPE PLUMBER	BASIS OF INSPECTION TRU 1593 M302		PHOTOS TAKEN YES / NO
CONTRACTORS NAME FIBER CONTROL			SAMPLE NO.		
ADDRESS 3010 BURNS AVE			CITY WANTACH		
STATE N.Y.			ZIP 11793		
LABORATORY NAME WARREN & PAUZE ENGINEERS PC			OWNERS NAME Beekman NYU Downtown Hospital		
ADDRESS 228 E 45TH ST			CITY N.Y.		
STATE N.Y.			ZIP 10017		
CONTACT PERSON:			TIME OF INSPECTION FROM: 9:30 am TO: 6:00 pm		
INSPECTION DISCLOSED:					

The Cleanup of the facade started from the Westside of the building and was completed and Visual inspection was done and no visible observed. The hospital entrance was cleaned and completed on 10/11 including the Eastside facade on Spruce St on 10/12 and Gold St on 10/13. All the exterior facade were inspected after the Cleanup and no visible debris observed. The Conventual hospital facade Cleanup started on the 14 of October 2002 after the Construction of scaffolds. The Cleanup continued and completed on 10/25/02. Visual inspection was done after the Cleanup and no visible debris observed.

NOV #	INFRACTIONS	RESULT CODE 5
NOV #		SUPERVISORS INITIALS R.L.

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access 4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

FILE