

WTC Visual Survey Form

Premise Address: <u>134 Beekman Street</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____ _____					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____ _____ _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments _____ _____ _____ _____					

Date: 4/20/2002

Inspection Team: Name: Robin Okello Agency: _____
Name: Sam Nebedum Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 20, 2002

Building Owner Name: _____

Address: _____

1134 Beckman St

Subject: _____

134 Beckman St

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



www.nyc.gov/dep

(718) DEP-HELP

Page: 1 Document Name: Extra

```

04/24/02                N.Y.C. DEPARTMENT OF BUILDINGS                BISPI031
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
134..... BEEKMAN STREET..... 1 MANHATTAN        10038 BIN# 1001344
DCP GEOGRAPHICAL INFORMATION:
BEEKMAN STREET          134 - 134                HEALTH AREA : 77      TAX BLK: 97...
                                           CENSUS TRACT: 11006   TAX LOT: 45...
                                           COMMUNITY BD: 101     CONDO :
                                           MULTI STRUCT: 1      CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : 134 BEEKMAN PROPRTIE           134 BEEKMAN PROPRTIE
CORP. NAME :                                LPC LANDMARK STATUS: LANDMARK
ADDRESS : 140 E 80TH ST                      DOB LOCAL LAW STATUS: NO
NEW YORK NY 10021-0306
DOF BUILDING INFORMATION:                    TRANS LAND VALUE: 0
BLDG SIZE: ** UNKNOWN **                     TAX EXEMPT FLAG : NO
LOT SIZE: ** UNKNOWN **                     TAX EXEMPT CLASS:
BLDG CLASS : K9 STORE BUILDING                CITY OWNERSHIP : NO
STORIES : 0                                UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE: MGMT CODE:              MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:
-----
PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN
    
```

Date: 4/24/ 2 Time: 02:19:42 PM

Page: 1 Document Name: Extra

04/24/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
134..... BEEKMAN STREET..... 1 MANHATTAN 10038 BIN# 1001344
DCP GEOGRAPHICAL INFORMATION:
BEEKMAN STREET 134 - 134 HEALTH AREA : 77 TAX BLK: 97...
CENSUS TRACT: 11006 TAX LOT: 45...
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : 134 BEEKMAN PROPRTIE 134 BEEKMAN PROPRTIE
CORP. NAME : LPC LANDMARK STATUS: LANDMARK
ADDRESS : 140 E 80TH ST DOB LOCAL LAW STATUS: NO
NEW YORK NY 10021-0306
DOF BUILDING INFORMATION: TRANS LAND VALUE: 0
BLDG SIZE: ** UNKNOWN ** TAX EXEMPT FLAG : NO
LOT SIZE: ** UNKNOWN ** TAX EXEMPT CLASS:
BLDG CLASS : K9 STORE BUILDING CITY OWNERSHIP : NO
STORIES : 0 UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 4/24/ 2 Time: 02:19:42 PM