

WTC Visual Survey Form

1000850

Premise Address: <u>44 Beaver & 42 Beaver.</u>		
Block: <u>29</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>73</u>	Mix Use ☐ Other ☒ <u>NYC DOS</u>	<u>DOS.</u>
# of Stories: <u>12</u>	AKA's:	
Building Owner/Management: <u>DOS.</u>		Telephone Number: <u>(718) 334-9100</u>
Name: <u>Director of Bldg. / Frank Conroy</u>		FAX: <u>()</u>
Address: <u>Beaver & Bldg. Maint.</u>		
On Site Contact: <u>Bldg. Mgr.</u>		Telephone Number: <u>(212) 837-8247</u>
Name: <u>Carlos Soto</u>		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: <u>Facade work scheduled in next 2 to 3 weeks</u>		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:**Facade:**

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible / Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible / Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible / Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible / Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

RoofDebris: ☒ ~~No Visible~~ / Fine Layer ☐ ½ to 1" ☐ > 1"Description: Gravel roof debris observed below gravel in several locations. on elevator motor room roof and inside gutters debris observed**Setbacks** N/A ☒

Floor: _____	Debris: ☐ No Visible / Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible / Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible / Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible / Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible / Fine Layer	☐ ½ to 1"	☐ > 1"

CommentsDate: 3/12/2002Inspection Team: Name: RAMMOHANAgency: NYC DEP

Name: _____ Agency: _____



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

March ~~February~~ 2, 2002

Building Owner Name: The Building Manager

Address: Dept. of Sanitation
B3M

Subject: 44 & 42 BEAVER ST. NYC

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:



building facade(s)

setback(s)

roof

other, elevator motor room roof / cooling tower roof

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by ~~February 12~~ February 27, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
for R. Radhakrishnan, P.E.

Director

Asbestos Control Program





**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422



March. ~~February~~ 2, 2002

The Building Manager.
Building Owner Name: Dept. of Sanitation

Address: BBM

Subject: 44 & 42 BEAVER ST. NYC

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
for **R. Radhakrishnan, P.E.**
Director
Asbestos Control Program

Page: 1 Document Name: Extra

03/02/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
44..... BEAVER STREET..... 1 MANHATTAN 10004 BIN# 1000850
DCP GEOGRAPHICAL INFORMATION:
BEAVER STREET 38 - 46 HEALTH AREA : 77 TAX BLK: 29...
SOUTH WILLIAM STREET 8 - 8 CENSUS TRACT: 1001 TAX LOT: 73...
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : SANITATION SANITATION
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 125 WORTH ST DOB LOCAL LAW STATUS: NO
NEW YORK NY 10013-4006
DOF BUILDING INFORMATION: TRANS LAND VALUE: 7,400,000
BLDG SIZE; 0098.75 X 0072.42 TAX EXEMPT FLAG : NO
LOT SIZE: 0098.75 X 0072.42 TAX EXEMPT CLASS:
BLDG CLASS : 03 OFFICE BUILDING CITY OWNERSHIP : YES
STORIES : 2 UPDATE DATE : 02/28/02
FOR CITY } MGMT TYPE: S MGMT CODE: 240 MGMT CODE NAME: SANIT
OWNERSHIP } MGMT HOLDER CODE: 240 MGMT HOLDER CODE NAME: SANIT

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 3/2/ 2 Time: 04:14:51 PM