

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**

JOEL A. MIELE, SR., P.E.
COMMISSIONER

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____

Date Sampled: 2-24-02

Premise: 17 BATTERY PLACE

Boro: MANHATTAN

Time: 11:20 am pm

Inspector: SAM NEBEDUM
Print

Samuel Nebedum
Signature

Turnaround Time : Immediate ☒ 24 Hours ☐ 48 Hours ☐ 1 Week ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20224/A038001	Fibrous	Courtyard	
2. 20224/A038002		Ledge	
3. 20224/A038003		Courtyard	
4. 20224/A038004			
5. 20224/A038005			
6. 20224/A038006			
7. 20224/A038007			
8. 20224/A038008			
9. 20224/A038009			
10. 20224/A038010			

ANALYSIS REQUESTED: Asbestos PLM ☒

Asbestos TEM ☐

Lead ☐

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**

JOEL A. MIELE, SR., P.E.
COMMISSIONER

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____

Date Sampled: 2-24-02

Premise: 17 BATTERY PLACE

Boro: MANHATTAN

Time: 12:00 am/pm

Inspector: SAM NEBEDUM
Print

Samuel Nebedum
Signature

Turnaround Time : Immediate ☒ 24 Hours ☐ 48 Hours ☐ 1 Week ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20224/A038011	Fibrous	AWNING	
2. 20224/A038012			
3. 20224/A038013			
4. 20224/A038014			
5. 20224/A038015			
6.			
7.			
8.			
9.			
10.			

ANALYSIS REQUESTED: Asbestos PLM ☒

Asbestos TEM ☐

Lead ☐

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME	<u>Carl Lutchmedine</u>	BADGE #	<u>A058</u>	DATE	<u>2/24/02</u>
LOCATION	<u>17 Battery Place</u>				

Roof - Clean
Facade - Not Cleaned

West

South

17 Battery Pl.

Washington St

North


→ 2 Washington St

Samples A038 - 0 - 2

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME 1-7-3 (ARC) LUTCHMANN BADGE # A038 DATE 2/24/02
 LOCATION 17 Battery Place

Roof - Clean
 Facade - Not Cleaned



Samples A038-0-1-2

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME 1-7-8 (AR) Lutzmann BADGE # 1018 DATE 2/24/02

LOCATION 17 Battery Place

Roof = Clean
Pavement = Not Clean

Work

Sample 4038-0-2