

Asbestos Inspection Report

Premise No. 47 ANN STREET					Inspection Date: 06-26-02	
Floor ROOF	Zip	Borough 1	Block 92	Lot 1T	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken Yes (No)
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name 47 ANN STREET ASSOCIATES LLC		
Address City 228 East 45 Street New York				Address City 47 ANN STREET NEW YORK		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone NY (212) 706-3030		
Contact Person				Time of Inspection from: AS NOTED		

WEDNESDAY JUNE 26 2002

8:00AM WORKERS BEGIN CLEAN-UP ACTIVITIES ON THE ROOF OF THE PREMISE.

8:45AM JOHN BURGESS OF WARREN & PANZER ENGINEERS BEGINS AIR SAMPLING FOR THIS PROJECT (CERTIFICATE # AH 97-11398 EXP 09/02) FIVE SAMPLES ARE RUN. LOCATIONS ARE AS FOLLOWS: 1 @ REMOTE DECON, 1 @ DOORWAY ENTRANCE TO ROOF WORK AREA AND 3 ON THE ROOF (IN THE WORK AREA).

12:00PM WORK PROCEEDS AS PER THE APPROVED SCOPE OF WORK.

5:00PM WORKERS BEGIN BAG-OUT ACTIVITIES, ACTIVE CLEAN-UP ACTIVITIES CEASE FOR THE DAY.

6:00PM WORKERS LEAVE THE JOBSITE.

THURSDAY JUNE 27 2002

8:00AM WORKERS RESUME CLEAN-UP ACTIVITIES.

12:00PM WORKERS COMPLETE ROOF CLEAN UP AND BEGIN BAG-OUT OF WASTE MATERIALS GENERATED BY THE CLEAN-UP WORK.

5:00PM I CONDUCT A VISUAL INSPECTION OF THE ROOF WORK AREA AND FIND IT CLEAN. NO VISIBLE WTC DEBRIS WAS OBSERVED.

