

Asbestos Inspection Report

Premise No. 49 ANN STREET					Inspection Date: 06-11-02	
Floor ROOF	Zip	Borough 1	Block 92	Lot 14	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken Yes/No ☒
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: 8 ⁰⁰ AM - 7 ⁰⁰ PM		
8 ⁰⁰ AM I ARRIVE ONSITE. THE CLEAN UP OF THE SET BACK ROOF AREA WHICH WAS BEGUN YESTERDAY IS IN PROGRESS. I REQUEST AND I AM PRESENTED WITH VALID NYC DEP AND NYS DOL ASBESTOS HANDLER AND ASBESTOS HANDLER SUPERVISOR CERTIFICATES. WARREN & PANZER'S REP LARRY BAER (AK 8900814 EXP DATE 02/03) IS ONSITE FOR THE AIR SAMPLING.						
9 ⁰⁰ AM - 9 ³⁰ AM AIR SAMPLING BEGUN AT THE FOLLOWING LOCATIONS: 1 SAMPLE RUN AT THE GFI ELECTRICAL PANEL. 2 SAMPLES RUN ON THE HIGHER ROOF AT 49 ANN STREET AND 2 SAMPLES RUN ON THE ST ANN STREET ROOF (ADJACENT TO THE SET-BACK AREA).						
11 ⁰⁰ AM SET-BACK ROOF CLEAN-UP CONTINUES.						
12 ⁰⁰ PM SET BACK ROOF CLEAN-UP IS COMPLETED. WORK ON THE ROOF OF 49 ANN WILL COMMENCE SHORTLY.						
4 ⁰⁰ PM WORK ON THE ROOF OF 49 ANN STREET IS IN PROGRESS. ALL WORK IS BEING PERFORMED AS PER THE APPROVED SCOPE OF WORK.						
6 ⁰⁰ PM ABATEMENT WORKERS BEGIN BAGGING-OUT WASTE MATERIALS GENERATED FROM THE CLEAN-UP ACTIVITIES.						
7 ⁰⁰ PM BAG-OUT ACTIVITIES ARE COMPLETED. WORKERS AND I LEAVE THE WORK SITE.						

RL

Asbestos Inspection Report

Premise No. 49 ANN STREET					Inspection Date: 06-11-02	
Floor ROOF	Zip	Borough 1	Block	Lot	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken Yes/No ☒
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: 8 ⁰⁰ AM - 7 ⁰⁰ PM		
8 ⁰⁰ AM I ARRIVE ONSITE. THE CLEAN UP OF THE SET BACK ROOF AREA WHICH WAS BEGUN YESTERDAY IS IN PROGRESS. I REQUEST AND I AM PRESENTED WITH VALID NYC DEP AND NYS DOL ASBESTOS HANDLER AND ASBESTOS HANDLER SUPERVISOR LICENSES. WARREN & PANZER'S REP LARRY BAER (AK 8900814 EXP DATE 02/03) IS ONSITE FOR THE AIR SAMPLING.						
9 ⁰⁰ AM - 9 ³⁰ AM AIR SAMPLING BEGUN AT THE FOLLOWING LOCATIONS: 1 SAMPLE RUN AT THE GFI ELECTRICAL PANEL. 2 SAMPLES RUN ON THE HIGHER ROOF AT 49 ANN STREET AND 2 SAMPLES RUN ON THE ST ANN STREET ROOF (ADJACENT TO THE SET-BACK AREA).						
11 ⁰⁰ AM SET-BACK ROOF CLEAN-UP CONTINUES.						
12 ⁰⁰ PM SET BACK ROOF CLEAN-UP IS COMPLETED. WORK ON THE ROOF OF 49 ANN WILL COMMENCE SHORTLY.						
4 ⁰⁰ PM WORK ON THE ROOF OF 49 ANN STREET IS IN PROGRESS. ALL WORK IS BEING PERFORMED AS PER THE APPROVED SCOPE OF WORK.						
6 ⁰⁰ PM ABATEMENT WORKERS BEGIN BAGGING-OUT WASTE MATERIALS GENERATED FROM THE CLEAN-UP ACTIVITIES.						
7 ⁰⁰ PM BAG-OUT ACTIVITIES ARE COMPLETED. WORKERS AND I LEAVE THE WORK SITE.						

Asbestos Inspection Report

Premise No. <u>49 ANN STREET</u>	Inspection Date: <u>06-12-02</u>
Inspector Dennis Antzoulatos	Page <u>2</u> of <u>2</u>

WEDNESDAY JUNE 12 2002

5:30 PM I CONDUCT A VISUAL INSPECTION OF THE CLEANED WORK AREA
AND FIND THAT THE WORK AREA IS FREE OF VISIBLE WTC
DEBRIS. THE PROJECT IS NOW COMPLETED.