

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 03/05/2002 03:49 PM

Submitted By

Page 1

Service # 416516

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 57 ANN ST 1

10038
Cross Streets NASSAU ST
WILLIAM ST

Compass Direction

Building ID 10012

Block 00092

Lot 0010

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 03/04/2002 11:53

Taken By 7244

MORALES, ANN K.

Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ.MAT)

Priority

Scheduled Date

Inspector

Due Date

Asset

Avg Insp Duration

☐ Customer Contact Req

Budget #

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

COMPLETED

Problem Comments

Initial Caller

Last Name

PII

Title MR

First Name, MI

Address

47 ANN ST

APT# PII

City, State/Province, ZIP/PC

☐ Foreign

Day Phone

PII

Evening Phone

PII

Call Date 03/04/2002 11:53

Reference #

Caller Comments

57 Ann St: parking lot rooftop has never been cleaned off since 9/11 attack. Severe dust, possible asbestos flying into callers home, which is two flights above rooftop. Called Asbestos Unit & spoke with Taryn at 11:43am.

Inspected

Resolution

By

CARL

Date

3/7/02

Time

12:30^p

Code

2

Date

3/7/02

Time

12:45^p

Wednesday 11:00 Am - 1:00 pm

No one at home. DEP is aware of debris on garage roof. Owner has been notified to clean up.

Carl

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 03/04/2002 12:04 PM

Submitted By

Page 1

Service # 416516

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 57 ANN ST 1

10038

Cross Streets NASSAU ST

WILLIAM ST

Compass Direction

Building ID 10012

Block 00092

Lot 0010

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 03/04/2002 11:53

Taken By 7244

MORALES, ANN K.

Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ.MAT)

Priority

Scheduled Date

Inspector

Due Date

Asset

Avg Insp Duration

☐ Customer Contact Req

Budget #

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

Problem Comments

Initial Caller

Last Name

PII

Title MR

First Name, MI

Address

47 ANN ST

APT PII

City, State/Province, ZIP/PC

☐ Foreign

Day Phone

PII

Evening Phone

PII

Call Date 03/04/2002 11:53

Reference #

Caller Comments

57 Ann St: parking lot rooftop has never been cleaned off since 9/11 attack. Severe dust, possible asbestos flying into callers home, which is two flights above rooftop. Called Asbestos Unit & spoke with Taryn at 11:43am.

Inspected

Resolution

By

Date

Time

Code

Date

Time

Left my telephone #
Not at his apt on the roof of 57 Ann Street
Do not need to call