

Asbestos Inspection Report

Premise No. 57 ANN STREET					Inspection Date: 06-11-02	
Floor ROOF	Zip	Borough 1	Block 92	Lot 10	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type PARKING GARAGE		Basis of Inspection WTC Survey		Photos Taken Yes ☒ No ☐
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person WILLIS MOORE				Time of Inspection from: 10 ⁰⁰ AM - 4 ⁰⁰ PM		
10⁰⁰ AM I CONDUCTED A VISUAL INSPECTION OF THE ROOF AND FIRE ESCAPE AREAS AFTER THE CLEAN UP OF DEBRIS WAS COMPLETED. THE CONCRETE ROOF OF THE PARKING GARAGE WAS FREE OF ANY VISIBLE WTC DEBRIS. THE METAL FIRE ESCAPES STILL REQUIRE SOME MINOR SPOT CLEANING. THE AREAS OF SPOT CLEANING WERE POINTED OUT TO THE ASBESTOS HANDLER SUPERVISOR ASSIGNED TO THIS PROJECT. 3⁰⁰ PM A VISUAL INSPECTION IS CONDUCTED OF THE METAL FIRE ESCAPES WHICH REQUIRED THE SPOT CLEANING. THE RE-INSPECTED AREAS WERE FOUND TO BE FREE OF VISIBLE WTC DEBRIS. 4⁰⁰ PM I LEAVE THE WORKSITE. THE REMOTE DECONTAMINATION UNIT WILL REMAIN FOR THE ONGOING CLEAN-UP ACTIVITIES AT 49 ANN STREET AND 55 ANN STREET.						

PP.