

OTHER
CHECKED
NO NOTES.
???

1001270

WTC Visual Survey Form

Premise Address: 57 ANN STREET		
Block: 92	Residential ☐ Commercial ☐	Name of Building:
Lot: 10	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: 57 ANN ST RLY ASSOC.		FAX: ()
Address: 57-61 ANN STREET		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:			
North ☐ N/A	Inspected ☐ Yes ☐ No	Debris ☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
South ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
East ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
West ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
Facade Description: _____			
Roof			
Debris: ☐ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"			
Description: _____			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Comments			
Ledges / Ventilation - Open Gargole - Unmarked Clean			
SOUND CLEAN-UP ASKED			

Date: **1/20/2002**

Inspection by: Name: **C.L.**

Agency: _____

Name: _____

Agency: _____

Page: 1 Document Name: Extra

02/22/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
57..... ANN STREET..... 1 MANHATTAN 10038 BIN# 1001270
DCP GEOGRAPHICAL INFORMATION:
ANN STREET 57 - 59 HEALTH AREA : 77 TAX BLK: 92...
CENSUS TRACT: 12011 TAX LOT: 10...
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : 57 ANN ST RLTY ASSOC INC 57 ANN ST RLTY ASSOC
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 1 COW LN DOB LOCAL LAW STATUS: NO
GREAT NECK NY 11024-1516
DOF BUILDING INFORMATION: TRANS LAND VALUE: 2,100,000
BLDG SIZE: 0053.00 X 0135.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0053.42 X 0115.50 TAX EXEMPT CLASS:
BLDG CLASS : G1 GARAGE/GAS STAT'N CITY OWNERSHIP : NO
STORIES : 3 UPDATE DATE : 01/12/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 2/22/ 2 Time: 10:17:51 AM



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

February 20, 2002

Building Owner Name: Lance Howard
Address: 57-61 Am St
NY
Subject: 57 Am St

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**
**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



February 2002



The City of New York
Department of Environmental Protection

59-17 Junction Boulevard
Corona, New York
11368-5107

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner

Bureau of Environmental Compliance
Tel (718) 595-4418
Fax (718) 595-4422

Building Owner Name:

Lance Howard

Address:

57-61 Ave St

NY NY

Subject:

57 Ave St
61 Ave St

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

☐
☐
☐
☒

building facade(s)

setback(s)

roof

other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by February 27, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

[Signature]

R. Radhakrishnan, P.E.
Director

Asbestos Control Program

