

FIBER CONTROL, INC.
 3010 BURNS AVENUE
 WANTAGH, NY 11793
 (516) 781-3000
 FAX (516) 781-3085

INVOICE

Revised 9-03-02

08/28/02

F1130

Date:

Inv. No.:

1

Due Date:

Page No.:

**BILL TO: New York City Dept of
 Environmental Protection
 Asbestos Control Program
 59-17 Junction Blvd
 Flushing, NY 11373-5108
 Att: Alphonso Plumptre
 Deputy Lab Director Supervising I.H.**

JOB SITE: job sites listed below

REFERENCE	TERMS	YOUR #	OUR #	SALES REP
TEL: 718-595-3671	Upon Completion	CONTRACT ROF-REM1	F1130	PG

DESCRIPTION		UNIT MEASURE	QUANTITY	UNIT PRICE		EXTENDED PRICE		
REFERENCE				ITEM DISCOUNT				
Exterior Cleanup								
<u>Address</u>		<u>Asphalt Roof</u>	<u>Unit Price</u>	<u>facade</u>	<u>Unit Price</u>	<u>Gravel Roof</u>	<u>Unit Price</u>	<u>Total</u>
22 Barclay Street		10710	@ \$1.48					
				7560	@ \$2.50			
								\$ 15,850.80
								\$ 18,900.00
16 Barclay Street		6426	@ \$1.48					
	front bldg			5670	@ \$2.50			\$ 9,510.48
	back bldg			2835	@ \$2.50			\$ 14,175.00
								\$ 7,087.50
14 Barclay Street		3150	@ \$1.48					\$ 4,662.00
45 Murray Street				2100	@ \$2.50			\$ 5,250.00
146 Chambers Street		1976	@ \$1.48					\$ 2,924.48
				1950	@ \$2.50			\$ 4,875.00
	rear setback	260	@ \$1.48					\$ 384.80
175 Broadway	rear			3000	@ \$2.50			\$ 7,500.00
177 Broadway	rear			3000	@ \$2.50			\$ 7,500.00
179 Broadway	rear			3000	@ \$2.50			\$ 7,500.00
181 Broadway	rear			3000	@ \$2.50			\$ 7,500.00
								\$ 113,620.06

WWW.ACTIONHAZMAT.COM

Perry Sheehy

SUB TOTAL	\$ 113,620.06
TAX	0.00
TOTAL	\$ 113,620.06

NET TO PAY

113 WTC
EMERGENCY
ON SITE
WILL BE
ACCEPTED



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107
ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)

TRU 1196 M 02
Building Dept. or TRU No
FOR OFFICIAL USE ONLY
1. NYC DEP
(See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 16 BARCLAY STREET Borough N.Y. Zip 10007
AKA ST PETER CHURCH RECTORY 3. Block 88 4. Lot 12
5. Type of Facility _____ 6. Name of Building _____

II. BUILDING OWNER

7. Name ARCHDIOCESE OF NEW-YORK 8. Contact Person FATHER MADIGAN
9. Tel. # (212) 233-8355 Fax # _____
10. Address 18 VESEY ST City N.Y. State N.Y. Zip 10007

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name FIBER CONTROL 13. Contact Person TONY COSTA
14. Federal Employer ID. # PII 15. Tel. # 516-781-3000 Fax # 516-781-3085
16. Address 3010 BURNS AVE City WANTASH State NY Zip 11793

V. THIRD PARTY AIR MONITOR

17. Name WARREN & PANZER ENGINEERS, PC 18. Contact Person MICHAEL NOLAN
19. Federal Employer ID. # _____ 20. Tel. # 212-922-0077 Fax # 212-922-0630
21. Address 228 EAST 45TH STREET City NEW YORK State NY Zip 10017
22. Sample Analysis Laboratory SCIENTIFIC LABORATORIES, LLC 23. NYS DOH ELAP # 11480

VI. PROJECT INFORMATION

24. Starting date for this portion of work 8/2/02 Projected completion date 9/2/02

Asbestos work schedule ☐ Monday ☐ Tuesday ☐ Wednesday ☐ Thursday ☐ Friday ☐ Saturday ☐ Sunday

Shift from: _____ ☐ am ☐ pm to _____ ☐ am ☐ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

14,931 Square Feet, and/or _____ Linear Feet



ACP
2/200

DEP
BUREAU OF ENVIRONMENTAL
REMEDATION & ENFORCEMENT
ASBESTOS CONTROL
PROGRAM
TRUG

ASBESTOS INSPECTION REPORT (continued)

26. Asbestos Hauler LOGANO NYS DEC Permit # CT-098 Tel. # 800-272-3867
 Disposal Site(s) SOUTHERN ALLEGHENIES, VALLEY LANDFILL

27. This asbestos abatement is part of a (Item a through e requires filing of this form with NYC Department of Buildings)

- a) ☐ Demolition b) ☐ Boiler Replacement c) ☐ Sprinkler Replacement d) ☐ Renovation/Alteration
 e) ☐ Fireproofing Replacement f) ☐ Other (Describe) _____

28. TYPE OF ABATEMENT (Check all appropriate boxes)

- ☐ Removal ☐ Enclosure ☐ Encapsulation ☐ Repair ☐ Clean up

29. ABATEMENT PROCEDURE (Check all appropriate boxes)



- ☐ Full Containment ☐ Glovebag ☐ Tent ☐ DEP Variance Application

30. LOCATIONS OF ABATEMENT


TR 1196 Muor

Floor(s)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	AFFECTED SURFACES CONTAINING ACM (e.g. Pipe lagging, ceiling, plenum ducts, storage tanks, decking, etc.)	AMOUNT OF ACM		DESCRIPTION OF WORK BEING PERFORMED (e.g. running cable, installing fire sprinklers, removing and replacing boilers, etc.)
			SQUARE FEET	LINEAR FEET	
Roof	(ASPHALT)		6426		
FACADE	FRONT BLDG		5670		
FACADE	BACK BLDG		2835		

31. I hereby declare that the information provided herein is true and complete to the best of my knowledge. I am familiar with Federal, State and NYC laws and regulations applicable to asbestos related work.

<u>BOSUN OGUARAKE</u> Print Name of Air Monitor  Signature <u>06-03-02</u> Date	<u>ANTHONY COSTA</u> Print Name of Asbestos Contractor  Signature <u>6-3-02</u> Date	<u>ANTHONY COSTA</u> Print Name of Applicant (If other than Owner)  Signature <u>6-3-02</u> Date
--	---	---

32. I understand that as the owner of a building where asbestos abatement activity occurs, I am responsible for the performance of the asbestos abatement activities in accordance with the Asbestos Control Program Rules. I have contracted the third party air monitor who is completely independent of all parties involved in the asbestos project. I hereby declare that I have authorized the filing of this notification for the work specified herein.

Alfonso Plungetre  7/30/02
Print Name of Owner Signature Date

STAMPED COPY OF THIS FORM INCLUDING AMENDMENTS MUST BE AVAILABLE AT THE WORK SITE.

Any modification of information provided on this form must be reported immediately in writing directly to the NYC DEP ACP.

The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

08/16/2002 17:51 FAX 718 784 4085

003

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P. C.
 LABORATORY ID #: T02-08-081
 ANALYT. METHODOLOGY: AHERA
 FILTER TYPE: M.C.E.
 AVERAGE G.O. AREA (mm²): 0.012422

PROJECT: NYC DEP, St. Peter Church
 DATE OF REPORT: 08/16/02
 DATE OF ANALYSIS: 08/16/02
 EFFECTIVE FILTER AREA (mm²): 385

**ATHENICA**

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7490
 Fax. (718) 784-4085

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (L)	G.O. ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (direct, fm ³)	TOTAL ASBESTOS AIR CONC. (fibras/cm ³)	TOTAL ASBESTOS FILTER CONC. (ppt-fm ³)	AIR CONC. FOR STRUCT. 0.55<5µm	AIR CONC. FOR STRUCT. 5-25µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-08-081-1602	By entrance	1620	4	0.0497	0.0048	<0.0048	<20.13	NA	NA	NA	NA
02	T02-08-081-1603	Church step	1620	4	0.0497	0.0048	<0.0048	<20.13	NA	NA	NA	NA
03	T02-08-081-1604	Side walk	1620	4	0.0497	0.0048	<0.0048	<20.13	NA	NA	NA	NA
04	T02-08-081-1605	Center of alley	1620	4	0.0497	0.0048	0.0048	20.13	<0.0048	0.0048	NA	Anthroph.
05	T02-08-081-1606	Back of alley	1620	4	0.0497	0.0048	<0.0048	<20.13	NA	NA	NA	NA

ANALYST
 E. Dimitrakas

LABORATORY DIRECTOR
 Spiro Dongaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a free duplicate analysis.
- If AES Inc. did not conduct the sampling, the reported air concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athena Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

228 East 45th Street
New York, NY 10017
(212) 922-0877
Fax (212) 922-0530

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 1 OF 5

Fax (212) 922-0830

24 hr + 12

	12 hr ⁺ /a	6 hr ⁺ /a	3 hr ⁺ /a	Immediate +/a
1	100	100	100	100
2	100	100	100	100
3	100	100	100	100
4	100	100	100	100
5	100	100	100	100
6	100	100	100	100
7	100	100	100	100
8	100	100	100	100
9	100	100	100	100
10	100	100	100	100
11	100	100	100	100
12	100	100	100	100
13	100	100	100	100
14	100	100	100	100
15	100	100	100	100
16	100	100	100	100
17	100	100	100	100
18	100	100	100	100
19	100	100	100	100
20	100	100	100	100
21	100	100	100	100
22	100	100	100	100
23	100	100	100	100
24	100	100	100	100
25	100	100	100	100
26	100	100	100	100
27	100	100	100	100
28	100	100	100	100
29	100	100	100	100
30	100	100	100	100
31	100	100	100	100
32	100	100	100	100
33	100	100	100	100
34	100	100	100	100
35	100	100	100	100
36	100	100	100	100
37	100	100	100	100
38	100	100	100	100
39	100	100	100	100
40	100	100	100	100
41	100	100	100	100
42	100	100	100	100
43	100	100	100	100
44	100	100	100	100
45	100	100	100	100
46	100	100	100	100
47	100	100	100	100
48	100	100	100	100
49	100	100	100	100
50	100	100	100	100
51	100	100	100	100
52	100	100	100	100
53	100	100	100	100
54	100	100	100	100
55	100	100	100	100
56	100	100	100	100
57	100	100	100	100
58	100	100	100	100
59	100	100	100	100
60	100	100	100	100
61	100	100	100	100
62	100	100	100	100
63	100	100	100	100
64	100	100	100	100
65	100	100	100	100
66	100	100	100	100
67	100	100	100	100
68	100	100	100	100
69	100	100	100	100
70	100	100	100	100
71	100	100	100	100
72	100	100	100	100
73	100	100	100	100
74	100	100	100	100
75	100	100	100	100
76	100	100	100	100
77	100	100	100	100
78	100	100	100	100
79	100	100	100	100

P.O.

CLIENT: NYC Dep

W&P FILE #: 1079-09-02

LABORATORY:

PROJECT: Peacocks

ANALYSIS METHOD: PCM TEM TEM

LOCATION: ~~ST~~ Peter's Church

7400 AHERA EPA LEVEL II

6-20-20

TECHNICIAN

SAMPLE NUMBER	SAMPLE DESCRIPTION & LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START STOP	TIME ON OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
01	by Entrance	3		6 6	1930 2450	270	1620	
02	Church Stoop	3		6 6	1932 2452	270	1620	
03	side walk	3		6 6	1934 2404	270	1620	
04	Centre of Alley	3		6 6	1936 2406	270	1620	
05	Road of Alley	3		6 6	1938 2408	270	1620	
06	B.F.	1						
07	D.F.	1						
08	Copped Balance	1						
	/							
	/							

WARRANT

7480-80-201

SAMPLE BY: Colasfine MINNCS DATE 05/14/02

SIGNATURE: CDH 2002

RELEASED BY: Colasina Romero DATE: 8/19/07

SIGNATURE: C. J. [Signature]

RECEIVED BY: E. S. S. 16/02 DATE: 8/16/02

SIGNATURE: 

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

08/19/2002 16:31 FAX 718 784 4085

009

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY**CLIENT:** Warren & Padzer Engineers, P.C.**PROJECT:** NYC DEP, St. Peter Church**LABORATORY ID #:** T02-08-089**DATE OF REPORT:** 08/17/02**ANALYT. METHODOLOGY:** AHERA**DATE OF ANALYSIS:** 08/17/02**FILTER TYPE:** M.C.E.**EFFECTIVE FILTER AREA (mm²):** 385**AVERAGE G.O. AREA (mm²):** 0.012422**ATHENICA**

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7658

Fax. (718) 784-4085

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITV. (pgs/cc/cm ²)	TOTAL ASBESTOS AIR CONC. (g/cc/cm ²)	TOTAL ASBESTOS FILTER CONC. (pg./mm ²)	AIR CONC. FOR 0.5-5.0µm	AIR CONC. FOR 5-10µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-08-089-1647	East in church	1260	5	0.0621	0.0049	<0.0049	<16.10	NA	NA	NA	NA
02	T02-08-089-1648	West in church	1260	5	0.0621	0.0049	<0.0049	<16.10	NA	NA	NA	NA
03	T02-08-089-1649	North in church	1260	5	0.0621	0.0049	<0.0049	<16.10	NA	NA	NA	NA
04	T02-08-089-1650	South in church	1260	5	0.0621	0.0049	<0.0049	<16.10	NA	NA	NA	NA
05	T02-08-089-1651	Corner of Barclay St.	1260	5	0.0621	0.0049	<0.0049	<16.10	NA	NA	NA	NA

ANALYST
E. Siostek

LABORATORY DIRECTOR
Spiro Donganis**LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955**

- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

**2220 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

Fax (212) 922-0630

 $24 \text{ hr}^{-1}/\text{s}$ 12 hr^f/a 6 hr^f/a

Immediate +/a

P₂O₅

1

CLIENT: JCB

CLIENT: **ABC**

W&P FILE #:

W&P FILE #: 1079-01-02
LABORATORY: W & P

20

CONTACT: *m*

m. Wilson

PROJECT: W27C

PROJECT: W3TC
LOCATION: 51 12th Ave

**LABORATORY:
ANALYSIS METHOD:
circle one**

LABORATORY: A & P
ANALYSIS METHOD: PCM
circle one

	TEMP	TEMP	TEMP
EPA EVER			
CHERA			

TEM TEM

Source: *Journal of the American Statistical Association*, 1997, 92, 103-114.

TECHNICIAN:

2014

[illegible]

SAMPLE BY: O WBS-7-1602 DATE: 8/16/02
SIGNATURE:
RELEASED BY: O WBS-7-1602 DATE: 8/16/02
SIGNATURE:
RECEIVED BY: A. SIGAL DATE: 9/17/02
SIGNATURE:

102-08-089

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY


ATHENICA

ENVIRONMENTAL SERVICES INC.

Tel. (718) 764-7460

Fax. (718) 764-4085

CLIENT: Warren & Panzer Engineers, P.C.

LABORATORY ID #: T02-08-109

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

 AVERAGE G.O. AREA (mm²): 0.012422

PROJECT: NYC DEP, Saint Peter's Church

DATE OF REPORT: 08/21/02

DATE OF ANALYSIS: 08/21/02

 EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (ft)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITV. (detection/cm ²)	TOTAL ASBESTOS AIR CONC. (struc./cm ²)	TOTAL ASBESTOS FILTER CONC. (gr./mm ²)	AIR CONC. FOR STRUCT. 0.5-5µm	AIR CONC. FOR STRUCT. 5-25µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-08-109-1762	By entrance	1440	5	0.0621	0.0043	<0.0043	<16.10	NA	NA	NA	NA
02	T02-08-109-1763	Inside work area west	1440	5	0.0621	0.0043	0.0172	64.40	0.0086	0.0086	Chrys.	Anthroph.
03	T02-08-109-1764	Inside work area north	1440	5	0.0621	0.0043	<0.0043	<16.10	NA	NA	NA	NA
04	T02-08-109-1765	Inside work area center	1440	5	0.0621	0.0043	<0.0043	<16.10	NA	NA	NA	NA
05	T02-08-109-1766	Inside work area east	1440	5	0.0621	0.0043	0.0129	48.30	<0.0043	0.0129	Chrys.	Anthroph.

 ANALYST
E. Sioukri

 LABORATORY DIRECTOR
Spiro Dougaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- AIRBORNE ENVIRONMENTAL SERVICES INC. (AES INC.) is independent of any and all institutional personnel, including the client.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

08/21/2002 21:49 FAX 718 784 4085

002/005

220 East 45th Street
New York, NY 10017
(212) 822-0077
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C. AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 1 OF 2

P.O.

12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

W&P FILE #: 1079:01:02

CONTACT: Mr. MACE, Nolan

LABORATORY: NYC DEP

LLW#:

ANALYSIS METHOD: PCM TEM

SCA JOB#:

7400 AHERA EPA LEVEL II

TECHNICIAN:

CLIENT: NYC DEP

PROJECT: Facades

LOCATION: St Peter Church Broadway

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE		TIME		TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
				START	STOP	ON	OFF			
01	By Entrance	3		08	08	1500	1800	180	1440	
02	Inside Work Area West	3		08	08	1502	1802	180	1440	
03	Inside Work Area North	3		08	08	1504	1804	180	1440	
04	Inside Work Area Center	3		08	08	1506	1806	180	1440	
05	Inside Work Area East	3		08	08	1508	1808	180	1440	
06	B.F.	1								
07	B.F.	1								
08	Capped Blank	1								
/										

COMMENTS:

102-08-109

SAMPLE BY: Celestine Monika DATE: 08/19/02

SIGNATURE: Celestine Monika

RELEASED BY: Celestine Monika DATE: 08/19/02

SIGNATURE: Celestine Monika

RECEIVED BY: A. G. G. G. DATE: 8/21/02

SIGNATURE: A. G. G. G.

SAMPLE TYPE CODES			
1 - Blank	5 - Final Clearance (inside)		
2 - Pre-Abatement	6 - Final Clearance (outside)		
3 - During Abatement	7 - Personal		
4 - During Glove Bag Removal	8 - Background		

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

2228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0530

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 2 OF 2

P.O.

	12 hr ⁺ /a	6 hr ⁺ /a	3 hr ⁺ /a	Immediate ⁺ /a
1	100	100	100	100
2	100	100	100	100
3	100	100	100	100
4	100	100	100	100
5	100	100	100	100
6	100	100	100	100
7	100	100	100	100
8	100	100	100	100
9	100	100	100	100
10	100	100	100	100
11	100	100	100	100
12	100	100	100	100
13	100	100	100	100
14	100	100	100	100
15	100	100	100	100
16	100	100	100	100
17	100	100	100	100
18	100	100	100	100
19	100	100	100	100
20	100	100	100	100
21	100	100	100	100
22	100	100	100	100
23	100	100	100	100
24	100	100	100	100
25	100	100	100	100
26	100	100	100	100
27	100	100	100	100
28	100	100	100	100
29	100	100	100	100
30	100	100	100	100
31	100	100	100	100
32	100	100	100	100
33	100	100	100	100
34	100	100	100	100
35	100	100	100	100
36	100	100	100	100
37	100	100	100	100
38	100	100	100	100
39	100	100	100	100
40	100	100	100	100
41	100	100	100	100
42	100	100	100	100
43	100	100	100	100
44	100	100	100	100
45	100	100	100	100
46	100	100	100	100
47	100	100	100	100
48	100	100	100	100
49	100	100	100	100
50	100	100	100	100
51	100	100	100	100
52	100	100	100	100
53	100	100	100	100
54	100	100	100	100
55	100	100	100	100
56	100	100	100	100
57	100	100	100	100
58	100	100	100	100
59	100	100	100	100
60	100	100	100	100
61	100	100	100	100
62	100	100	100	100
63	100	100	100	100
64	100	100	100	100
65	100	100	100	100
66	100	100	100	100
67	100	100	100	100
68	100	100	100	100
69	100	100	100	100
70	100	100	100	100
71	100	100	100	100
72	100	100	100	100
73	100	100	100	100
74	100	100	100	100
75	100	100	100	100
76	100	100	100	100
77	100	100	100	100
78	100	100	100	100
79	100	100	100	

W&P FILE #: 1079:07:02

LABORATORY: Q7C

CLIENT: NYC DEP

PROJECT: Facades

LOCATION: St Peter Church, Penclaw

ANALYSIS METHOD:	PCM	TEM

SA circle one 7400 AHERRA EPA LEVER

TECHNICIAN: Colleen Jones

[illegible]

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE		TIME		TOTAL TIME	VOLUME (liters)	CONCENTR. (fib./cc.)
				START	STOP	ON	OFF			
09	by the Stepp ramp.	3		04	04	1800	0900	420	1680	
10	Front East Side	3		04	04	1802	0901	420	1680	
11	Front Centre Side	3		04	04	1804	0904	420	1680	
12	Front North Side	3		04	04	1806	0906	420	1680	
13	Front West Side	3		04	04	1808	0908	420	1680	
14	BF	1								
15	BF	1								
16	colled blank	1								

COMMENTS:

SAMPLE BY: Celestine Njiru DATE: 08/19/20

SIGNATURE: [Signature]

RELEASED BY: Carol Anne Dunning DATE: 08/19/00

SIGNATURE: W. J. [Signature]

RECEIVED BY: A. CASTIGALLO DATE: 8/21/02

SIGNATURE: _____

702-08-109

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

08/21/2002 21:50 FAX 718 784 4085

005/005

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY**ATHENICA**

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7480
Fax. (718) 784-4085CLIENT: Warren & Panzer Engineers, P.C.
LABORATORY ID #: T02-08-109
ANALYT. METHODOLOGY: AHERA
FILTER TYPE: M.C.E.
AVERAGE G.O. AREA (mm²): 0.012422PROJECT: NYCDEP, Saint Peter's Church
DATE OF REPORT: 08/21/02
DATE OF ANALYSIS: 08/21/02
EFFECTIVE FILTER AREA (mm²): 385**LABORATORY RESULTS**

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O.% ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (fibers/cm ²)	TOTAL ASBESTOS AIR CONC. (fibers/cm ³)	TOTAL ASBESTOS FILTER CONC. (ug/mm ²)	AIR CONC. FOR STRUCT. 0.5<5µm	AIR CONC. FOR STRUCT. 5>5.0µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
09	T02-08-109-1767	By the steps way	1680	4	0.0497	0.0046	<0.0046	<20.13	NA	NA	NA	NA
10	T02-08-109-1768	Front east side	1680	4	0.0497	0.0046	<0.0046	<20.13	NA	NA	NA	NA
11	T02-08-109-1769	Front center side	1680	4	0.0497	0.0046	<0.0046	<20.13	NA	NA	NA	NA
12	T02-08-109-1770	Front north side	1680	4	0.0497	0.0046	<0.0046	<20.13	NA	NA	NA	NA
13	T02-08-109-1771	Front west side	1680	4	0.0497	0.0046	<0.0046	<20.13	NA	NA	NA	NA

ANALYST
R. StonkciLABORATORY DIRECTOR
Spiro Dongaris**LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955**

- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc. did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

ASBESTOS INSPECTION REPORT

EMISE NO.		STREET				INSPECTION DATE	
16 Barclay		Street				7-30-02	
DOOR	ZIP	BORO CODE	BLOCK	LOT	SQUAD #	BADGE #	
R/F	10007	1	88	12	1	AD10	
INSPECTOR		BLDG TYPE	BASIS OF INSPECT.			PHOTOS TAKEN YES/NO	
Thomson Plumptre			TRU1196mo2				
CONTRACTORS NAME				SAMPLE NO.			
FIBER CONTROL							
ADDRESS				CITY			
3010 BURNS AVE				WANTAGH			
STATE		ZIP	PHONE	SAMPLE NO.			
N.Y		11793	(516) 781-3000				
LABORATORY NAME				OWNERS NAME			
WARREN & PAUZEER ENGINEERS, PC				Archdiocese of N.Y			
ADDRESS		CITY		ADDRESS		CITY	
228 E. 45TH ST		N.Y		18 Vesey St		N.Y	
STATE		ZIP	PHONE	STATE		ZIP	PHONE
N.Y		10017	(212) 922-0077	N.Y		10007	
CONTACT PERSON:				TIME OF INSPECTION FROM: 2:30 am/pm TO: 3:00 am/pm			
INSPECTION DISCLOSED:							

Inspected the front roof and it was cleaned without visible debris. But the back roof was not cleaned and the contractor had to clean it including the lower portions of joint entrance way of the church and lower building. Follow up still necessary for the facade.

The cleanup of the facade started on 8/14/02 at 7:00 pm. During the course of the facade cleanup, a photographer from FEMA - Mr. Hansen Hobart who took photographs of the cleanup.

The cleanup of the front and side facade was completed on 8/14/02 and the rear facade was done on the 19th of August 2002. Visual inspection was done after the completion and no visible debris observed.

NOV #	INFRACTIONS					RESULT CODE
						5
NOV #						SUPERVISORS INITIALS
						R

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family
D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access
4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 3093