

Page: 1 Document Name: Extra

```

03/05/02                N.Y.C. DEPARTMENT OF BUILDINGS                BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
16..... BARCLAY STREET..... 1 MANHATTAN        10007 BIN# 1001239
DCP GEOGRAPHICAL INFORMATION:
BARCLAY STREET          16 - 16                HEALTH AREA : 77        TAX BLK: 88...
CENSUS TRACT: 1007      TAX LOT: 12...
COMMUNITY BD: 101      CONDO :
MULTI STRUCT: 1        CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE:  DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : CH OF ST PETER                CH OF ST PETER
CORP. NAME :                               LPC LANDMARK STATUS: NO
ADDRESS : 16          BARCLAY ST           DOB LOCAL LAW STATUS: NO
NEW YORK NY 10007-2705
DOF BUILDING INFORMATION:                  TRANS LAND VALUE: 905,000
BLDG SIZE; 0024.00 X 0101.08              TAX EXEMPT FLAG : YES
LOT SIZE: 0024.83 X 0101.08              TAX EXEMPT CLASS: X5
BLDG CLASS : M1 CHURCH, SYNAGOGUE         CITY OWNERSHIP : NO
STORIES : 5                             UPDATE DATE : 02/28/02
FOR CITY } MGMT TYPE:      MGMT CODE:      MGMT CODE NAME:
OWNERSHIP }      MGMT HOLDER CODE:      MGMT HOLDER CODE NAME:
-----
PF1 =PREV  PF2 =MAIN  PF7 = NEW ADDRESS  PF8 = NEW BLK/LOT  PF9 = NEW BIN

```

3/5 Roof has
visible debris
Mohan

Date: 3/5/ 2 Time: 04:58:59 PM

ASBESTOS INSPECTION REPORT

REMISE NO.		STREET				INSPECTION DATE	
16 Barclay		Street				7-30-02	
LOOR	ZIP	BORO CODE	BLOCK	LOT	SQUAD #	BADGE #	
R/F	10007	1	88	12	1	AD10	
INSPECTOR		BLDG TYPE	BASIS OF INSPECT.			PHOTOS TAKEN YES / NO	
ALPHONSO PLUMPTRE			TRU1196mo2				
CONTRACTORS NAME				SAMPLE NO.			
FIBER CONTROL							
ADDRESS				SAMPLE NO.			
3010 BURNS AVE							
CITY		WANTAGH					
STATE	ZIP	PHONE					
N.Y.	11793	(616) 781-3000					
LABORATORY NAME				OWNERS NAME			
WARREN & PANZER ENGINEERS, PC				Archdiocese of N.Y.			
ADDRESS		CITY		ADDRESS		CITY	
238 E. 45TH ST		N.Y.		18 Vesey St		N.Y.	
STATE	ZIP	PHONE					
N.Y.	10017	(212) 922-0077					
CONTACT PERSON:				TIME OF INSPECTION FROM: TO:			
				2:30 am/pm TO: 3:00 am/pm			
INSPECTION DISCLOSED:							

Inspected the front roof and it was cleaned without visible debris. But the back roof was not cleaned and the contractor had to clean it including the lower portions of joint entrance way of the church and lower building. Follow up still necessary for the facade.

The cleanup of the facade started on 8/14/02 at 7:00 pm. During the course of the facade cleanup, a photographer from FEMA - Mr. Hansen Hobart who took photographs of the cleanup.

The cleanup of the front and side facade was completed on 8/14/02 and the rear facade was done on the 19th of August 2002. Visual inspection was done after the completion and no visible debris observed.

NOV #	#INFRCTIONS					RESULT CODE
						5
NOV #						SUPERVISORS INITIALS
						R

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family
D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access
4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 3093

FILE