

## ASBESTOS INSPECTION REPORT

|                              |       |                |                      |                                                    |              |                 |  |          |
|------------------------------|-------|----------------|----------------------|----------------------------------------------------|--------------|-----------------|--|----------|
| REMISE NO.                   |       | STREET         |                      |                                                    |              | INSPECTION DATE |  |          |
| 22 Barclay St                |       |                |                      |                                                    |              | 7-30-02         |  |          |
| LOOR                         | ZIP   | BORO CODE      | BLOCK                | LOT                                                | SQUAD #      | BADGE #         |  |          |
| R/F                          | 10007 | 1              | 88                   | 11                                                 | 1            | AD10            |  |          |
| INSPECTOR                    |       | BLDG TYPE      | BASIS OF INSPECT.    |                                                    | PHOTOS TAKEN |                 |  | YES / NO |
| ALPHONSO PLUMPTRE            |       |                | R-1197MN02           |                                                    |              |                 |  |          |
| CONTRACTORS NAME             |       |                |                      | SAMPLE NO.                                         |              |                 |  |          |
| FIBER CONTROL                |       |                |                      |                                                    |              |                 |  |          |
| ADDRESS                      |       |                |                      | SAMPLE NO.                                         |              |                 |  |          |
| 3010 BURNS AVE CITY WANTAGH  |       |                |                      |                                                    |              |                 |  |          |
| STATE                        | ZIP   | PHONE          | SAMPLE NO.           |                                                    |              |                 |  |          |
| N.Y.                         | 11793 | (916) 781-3000 |                      |                                                    |              |                 |  |          |
| LABORATORY NAME              |       |                |                      | OWNERS NAME                                        |              |                 |  |          |
| WARREN & PANZER ENGINEERS PC |       |                |                      | N.Y. Archdiocese                                   |              |                 |  |          |
| ADDRESS                      |       |                |                      | ADDRESS                                            |              |                 |  |          |
| 228 E. 45TH ST CITY N.Y.     |       |                |                      | 18 Vesey St CITY N.Y.                              |              |                 |  |          |
| STATE                        | ZIP   | PHONE          | STATE                |                                                    |              |                 |  |          |
| N.Y.                         | 10017 | (212) 922-0077 | N.Y. ZIP 10007 PHONE |                                                    |              |                 |  |          |
| CONTACT PERSON:              |       |                |                      | TIME OF INSPECTION FROM: 1:30 am/pm TO: 2:15 am/pm |              |                 |  |          |
| INSPECTION DISCLOSED:        |       |                |                      |                                                    |              |                 |  |          |

I inspected the Church roof and I did observe that there wasn't any visible debris on top of it including the gutters. Follow up still necessary for the the Facade Cleanup.

The cleaning of the facade started on 8/15/02 at 7pm from the Westside of the Church. The entire westside facade was washed and was later inspected and there were no visible debris observed on it.

The Eastside of the Church facade continued on 8/16/02 at 10:00am and was completed at about 6:00pm. No visible debris observed after the Cleanup. The front of the Church facade was done on 8/19/02 and no visible debris observed after the Cleanup.

|       |             |  |  |  |  |                      |
|-------|-------------|--|--|--|--|----------------------|
| NOV # | #INFRCTIONS |  |  |  |  | RESULT CODE          |
|       |             |  |  |  |  | 5                    |
| NOV # |             |  |  |  |  | SUPERVISORS INITIALS |
|       |             |  |  |  |  | RL                   |

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family  
D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access  
4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 308C

FILE