

WTC Visual Survey Form

Premise Address: 115 Chambers St		
Block:	Residential ☐ Commercial ☒	Name of Building: DC 37
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: (212) 367-1134
Name: Ralph Pepe		FAX: ()
Address:		
On Site Contact:		Telephone Number: (718) 212-7664
Name: Thomas Cabrera		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Windows always cleaned every month.

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

The exterior and interior are cleaned.

Date: 1/24/2002

Inspection Team: Name: _____

Name: _____

Agency: _____

Agency: _____

WTC Visual Survey Form

f

Premise Address: <u>115 Chambers St</u>		
Block: Lot:	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building: <u>DC 37</u>
# of Stories:	AKA's:	
Building Owner/Management: Name: <u>Ralph Pepe</u>		Telephone Number: <u>(212) 367-1124</u> FAX: ()
Address:		
On Site Contact: Name: <u>Thomas Cabrera</u>		Telephone Number: <u>(718) 212-7666</u> <u>4440</u>
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Windows always cleaned every month.

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

The exterior and interior are cleaned.Date: 1/24/2002

Inspection Team: Name: Alphonso P. Livingston Agency: NYC DEP
 Name: Mr. Horton Agency: NYSDOL

9



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

February 23, 2002

District Counsel 37B
140 Park Place
New York, NY 10007-2149

**Subject: 115 CHAMBERS STREET
117 Chambers St
Second Notice**

Dear Sir/ Madam:

This is a follow-up to the NYC DEP request for copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. To date, our office has not received the requested documents and information. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E.
Director
Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP