



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Flushing, New York
11373-5108

**Christopher O. Ward
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental
Compliance**

Tel (718) 595-4418
Fax (718) 595-4422

September 3, 2002

TO: Saint George Episcopal
135-32 38th Avenue
Flushing, NY 11354-4417

RE: 116 CHAMBERS STREET

FINAL NOTICE

Dear Saint George Episcopal Building Owner:

I am writing with regard to 116 CHAMBERS STREET which was inspected by DEP on 09/03/02. During this inspection, debris from the collapse of the World Trade Center towers was observed on the exterior surfaces of the building.

You have been previously contacted with regard to participating in DEP's Lower Manhattan Building Cleaning Program. Under this program, contractors retained by DEP will clean all exterior building surfaces affected by World Trade Center debris at no cost to the building owner.

The Building Cleaning Program is now drawing to a close, and we have yet to receive a response from you regarding your participation. If you do not participate in the Program, the building will be scheduled for another DEP inspection in the near future. If that inspection shows that there is still visible debris from the World Trade Center on the exterior of the building, samples will be collected. If laboratory analysis of these samples shows that the debris is asbestos-containing material, you will then be issued a Commissioner's Order directing you to retain a contractor to clean the exterior of the building. Such cleaning would be at your expense, and failure to comply with the Commissioner's Order could result in the issuance of notices of violation carrying penalties of up to \$10,000 per day.

You are strongly urged to take advantage of the Building Cleaning Program. A blank License Agreement has been attached for your convenience. Please fill in the appropriate information and sign and return the form as soon as possible.

If you have any questions, please call 718-595-3682 during office hours, or the 24-hour Help Center at 718-DEP-HELP. Your cooperation is greatly appreciated.

Sincerely,

A handwritten signature in black ink, appearing to read "R. Radhakrishnan".

R. Radhakrishnan, P.E.

Director

Asbestos Control Program



(718) DEP-HELP

WTC Visual Survey Form

Premise Address: <u>116 Chambers St</u>		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Visible debris on windows & ledges</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 9/13/2002Inspection Team: Name: AL

Agency: _____

Name: _____

Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

February 23, 2002

ST George Episcopal
135-32 38th Avenue
Flushing, NY 11354-4417

Subject: 116 CHAMBERS STREET
Second Notice

Dear Sir/ Madam:

This is a follow-up to the NYC DEP request for copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. To date, our office has not received the requested documents and information. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

A handwritten signature in black ink, appearing to read "R. Radhakrishnan".

R. Radhakrishnan, P.E.
Director
Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP

Page: 1 Document Name: Extra

01/30/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
116..... CHAMBERS STREET..... 1 MANHATTAN 10007 BIN# 1001485
DCP GEOGRAPHICAL INFORMATION:
CHAMBERS STREET 116 - 116 HEALTH AREA : 77 TAX BLK: 136..
CENSUS TRACT: 1002 TAX LOT: 24...
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : ST GEORGE EPISCOPAL ST GEORGE EPISCOPAL
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 13532 38TH AVE DOB LOCAL LAW STATUS: NO
FLUSHING NY 11354-4417
DOF BUILDING INFORMATION: TRANS LAND VALUE: 606,000
BLDG SIZE; 0025.00 X 0076.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0025.00 X 0076.00 TAX EXEMPT CLASS:
BLDG CLASS : 09 OFFICE BUILDING CITY OWNERSHIP : NO
STORIES : 5 UPDATE DATE : 01/12/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/30/ 2 Time: 11:58:20 AM