

WTC Visual Survey Form

(14)

Premise Address: <u>110 Chambers St.</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Broken windows etc. lightly dirty</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description: <u>No Access</u>					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 2/15 /2002Inspection Team: Name: ALAgency: _____
Name: _____ Agency: _____