

54 Residence - multiuse

135
16
WTC Visual Survey Form

Premise Address: 96-135 Chambers St.		
Block: 135 Lot: 18	Residential ☐ Commercial ☐ Mix Use ☒ Other ☐	Name of Building:
# of Stories: 5	AKA's:	
Building Owner/Management: Name: Herbert Moskowitz		Telephone Number: (212) 732-4040 FAX: (212) 212-234-1971
Address:		P11 274 12/12/02
On Site Contact: Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	Debris	☐ 1/2 to 1"	☐ > 1"
South	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Facade Description: <u>Broken windows etc.</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ 1/2 to 1" of dust ☐ > 1" of dust					
Description: <u>Debris on roof and in gutters. Contained in back</u> <u>needs to be inspected close up. Looks like metal debris.</u>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Comments					
<u>Need to contact owner and have him sample gutters</u> <u>and check debris on roof</u>					

Date: 1/29/2002

Inspection Team: Name: R. Fitzpatrick
Name: R. RamanathanAgency: US EPA
Agency: NYC DEP