

102 Chambers

**DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF ENVIRONMENTAL COMPLIANCE  
ASBESTOS AND LEAD CONTROL PROGRAM  
59-17 JUNCTION BOULEVARD  
CORONA, NY 11368  
JOEL A. MIELL, SR., P.E.  
COMMISSIONER**

**BULK  
ANALYSIS CHAIN OF CUSTODY**

Incident No.: \_\_\_\_\_

Date Sampled: 02/24/02Premise: 32 WARREN STREETBoro: MANHATTANTime: 11:20 am/pmInspector: DINESH SHAH

Print

DBShah

Signature

Turnaround Time: Immediate ☒ 24 Hours ☐ 48 Hours ☐ 1 Week ☐


| SAMPLE NUMBER     | DESCRIPTION  | LOCATION SAMPLED | LAB ID |
|-------------------|--------------|------------------|--------|
| 1. 20224/A060 019 | Fibrous Dirt | Roof             |        |
| 2. 20224/A060 020 | " "          | "                |        |
| 3. 20224/A060 021 | " "          | "                |        |
| 4. 20224/A060 022 | " "          | "                |        |
| 5. 20224/A060 023 | " "          | "                |        |
| 6. 20224/A060 024 | " "          | "                |        |
| 7. 20224/A060 025 | " "          | "                |        |
| 8. 20224/A060 026 | " "          | "                |        |
| 9. 20224/A060 027 | Fibrous Dirt | Roof             |        |
| 10.               |              |                  |        |

ANALYSIS REQUESTED: Asbestos PLM ☒Asbestos TEM ☐Lead ☐

| Date | Time     | Accepted By | Comments |
|------|----------|-------------|----------|
| 1.   | am<br>pm | Print       |          |
|      |          | Sign        |          |
| 2.   | am<br>pm | Print       |          |
|      |          | Sign        |          |
| 3.   | am<br>pm | Print       |          |
|      |          | Sign        |          |
| 4.   | am<br>pm | Print       |          |
|      |          | Sign        |          |
| 5.   | am<br>pm | Print       |          |
|      |          | Sign        |          |

MEP ACLP REV 5/00

2/24 On Warren St 32 Warren St  
 2nd from corner of church  
 roof appeared to be not claimed.



11:30