

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368
JOEL A. MIELE, SR., P.E.
COMMISSIONER**

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____

Date Sampled: 02/24/02Premise: 149 CHURCH STREETBoro: MANHATTANTime: 1:30 am pmInspector: DINESH SHAH
PrintD. Shah
SignatureTurnaround Time: Immediate ☒ 24 Hours ☐ 48 Hours ☐ 1 Week ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20224/A060 028	Fibrous Dirt	Roof	
2. 20224/A060 029	" "	"	
3. 20224/A060 030	" "	"	
4. 20224/A060 031	" "	"	
5. 20224/A060 032	" "	"	
6. 20224/A060 033	" "	"	
7. 20224/A060 034	" "	"	
8. 20224/A060 035	" "	"	
9. 20224/A060 036	Fibrous Dirt	Roof	
10.			


ANALYSIS REQUESTED: Asbestos PLM ☒Asbestos TEM ☐Lead ☐

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

DEP ACLP REVISION

2/24/02 149 Church St

Condition appeared to be same N
149 Chamber.



1:30 pm