

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**

JOEL A. MIELE, SR., P.E.
COMMISSIONER

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____

Date Sampled: 02/23/02

Premise: 102 Chamber St & 149 Church St.

Boro: Manhattan

Time: 4:00 am/pm

Inspector: DINESH SHAH

Print

Signature

Turnaround Time: Immediate ☒ 24 Hours ☐ 48 Hours ☐ 1 Week ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A060 030	Fibrous Dirt	Roof mid	
2. 20223/A060 031	Fibrous Dirt	Roof mid	
3. 20223/A060 032	Fibrous Dirt	Roof mid	
4. 20223/A060 033	Fibrous Dirt	Roof mid	
5. 20223/A060 034	Fibrous Dirt	Roof mid	
6. 20223/A060 035	Fibrous Dirt	Roof mid	
7. 20223/A060 036	Fibrous Dirt	Roof mid	
8. 20223/A060 037	Fibrous Dirt	Roof mid	
9. 20223/A060 038	Fibrous Dirt	Roof mid	
10.			

ANALYSIS REQUESTED: Asbestos PLM ☒

Asbestos TEM ☐

Lead ☐

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

DEP ACLP REV 5/00

ENTERED

2/23/02

102 chamber & 149 church.

Common Roof for both addresses.

102 chambers st N

W

E

S

3 1/2 ft.

