

WTC Visual Survey Form

Premise Address: <u>92 Chamber Street</u>		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☒ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management: <u>Hamberger Green & Haver</u>		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact: <u>The Restaurant Manager</u>		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:		
North ☐ N/A	Inspected ☒ Yes ☐ No	Debris ☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Facade Description: _____		
Roof		
Debris: ☒ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"		
Description: <u>Debris (mudlike near drains and in gutters)</u>		
Setbacks N/A ☒		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
Comments <u>need to contact the owner. No access. Roof inspected from the adjacent roof.</u>		

Date: 01/24/2002

Inspection Team: Name: R. Fitzpatrick
Name: R. RAMMCHAN

Agency: USEPA
Agency: NYC DEP

29