

WTC Visual Survey Form

Premise Address: 95 CHAMBERS ST		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>CLEANED</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>CLEANED. NO VISIBLE DEBRIS</u>					
<u>OBSERVED.</u>					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
?					

Date: 10/24/2002

Inspection Team: Name: AL

Agency: _____

Name: _____

Agency: _____

ENTERED

CLEANED BY OWNER

WTC Visual Survey Form

Premise Address: <u>95 Chambers St</u>		
Block: <u>149</u>	Residential ☐ Commercial ☒	Name of Building: <u>Ralph's Pearl St. Inc</u>
Lot: <u>11</u>	Mix Use ☐ Other ☐	
# of Stories: <u>5</u>	AKA's: <u>77 Reade St</u>	
Building Owner/Management:		Telephone Number: (212) 267-5567
Name: <u>KREM Chambers St Corp</u>		FAX: ()
Address:		
On Site Contact:		
Name: <u>Daniel Ades</u>		Telephone Number: (212) 267-5567
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☒ No		
Exterior Survey Performed ☐ Yes ☒ No		
General Clean Up ☒ Yes ☐ No	Locations: <u>All floors with damage, falling concrete</u>	
ACM Clean Up ☐ Yes ☒ No	Locations: <u>place panel come through roof</u>	
Air Monitoring ☐ Yes ☒ No	Locations: <u></u>	
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
North	☒ N/A	Inspected ☐ Yes ☐ No	Debris ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Facade Description: <u>Smaller windows etc</u>			
Roof			
Debris:	☐ No Visible /Fine Layer	☒ 1/2 to 1" of dust	☐ > 1" of dust.
Description: <u>1 ft² of debris/dust in southwest corner of roof. 1/150, some material down on street 3' square</u>			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Comments: <u>edges - R.</u>			
<u>Owner: Mordey Mizrahi 212-267-5567</u>			
<u>4th floor on 12502 - discuss getting material tested</u>			
<u>1 Story not west side (part of Ralph's) no access. Upstairs to be cleaned</u>			

Date: 1/24/2002Inspection Team: Name: R. FitzpatrickAgency: USEPAName: R. KramarzAgency: NYC DEP



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Flushing, New York
11373-5108

**Christopher O. Ward
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental
Compliance**

Tel (718) 595-4418
Fax (718) 595-4422

September 3, 2002

**TO: Rae Me Realty Inc.
95 Chambers Street
New York, NY 10007-1821**

**RE: 95 CHAMBERS STREET
77 Reade St
FINAL NOTICE**

Dear Rae Me Realty Inc.:

I am writing with regard to 95 CHAMBERS STREET which was inspected by DEP on 08/30/02. During this inspection, debris from the collapse of the World Trade Center towers was observed on the exterior surfaces of the building.

You have been previously contacted with regard to participating in DEP's Lower Manhattan Building Cleaning Program. Under this program, contractors retained by DEP will clean all exterior building surfaces affected by World Trade Center debris at no cost to the building owner.

The Building Cleaning Program is now drawing to a close, and we have yet to receive a response from you regarding your participation. If you do not participate in the Program, the building will be scheduled for another DEP inspection in the near future. If that inspection shows that there is still visible debris from the World Trade Center on the exterior of the building, samples will be collected. If laboratory analysis of these samples shows that the debris is asbestos-containing material, you will then be issued a Commissioner's Order directing you to retain a contractor to clean the exterior of the building. Such cleaning would be at your expense, and failure to comply with the Commissioner's Order could result in the issuance of notices of violation carrying penalties of up to \$10,000 per day.

You are strongly urged to take advantage of the Building Cleaning Program. A blank License Agreement has been attached for your convenience. Please fill in the appropriate information and sign and return the form as soon as possible.

If you have any questions, please call 718-595-3682 during office hours, or the 24-hour Help Center at 718-DEP-HELP. Your cooperation is greatly appreciated.

Sincerely,

A handwritten signature in cursive script, appearing to read "R. Radhakrishnan".

R. Radhakrishnan, P.E.

Director

Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP

WTC Visual Survey Form

Premise Address: <u>95 Chambers St</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>Rae M. Realty Inc</u>		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: <u>NA</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>Scattered WTC materials on roof.</u>					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 8/11/2002

Inspection Team: Name: AL

Agency: _____

Name: _____

Agency: _____