NYC 9/11 Public Portal Document

WTC Visual Survey Form

Premise Address: 95 Chambers St

Block: **Lot:** | Residential ☐ Commercial ☒ Mix Use ☐ Other ☐ _____ | **Name of Building:** Ralph's Pearl St. Inc.

# of Stories: 5 | **AKA's:**

Building Owner/Management:
Name: RAEM Chambers St Corp
Telephone Number: (2 2) 267 - 5567
FAX: ( )
Address:

On Site Contact:
Name: David Ades
Telephone Number: (212) 267-5567

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☒ No
Exterior Survey Performed ☐ Yes ☒ No
General Clean Up ☒ Yes ☐ No Locations: All floors w/min. damage, falling debris
ACM Clean Up ☐ Yes ☒ No Locations: plate mail room through roof
Air Monitoring ☐ Yes ☒ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: Brick windows etc

Roof

Debris: ☐ No Visible /Fine Layer (light dust) ☒ ½ to 1" (1 dust) ☐ > 1" (1 dust.)
Description: 1 ft² of debris/dust in southwest corner of roof. Also some shards of glass scattered 3' square

Setbacks N/A ☐

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

edges of K.
Owner Monty Mizrahi 212-267-5567
All floors on 1/25/02 to access getting material from
1 Story roof west side (part of Ralph's) no access upper to be done at

Date: 1 / 24 /2002
Inspection Team: Name: K Fitzpatrick Agency: USEPA
Name: K Cummings Agency: USACE

spoke from 9th Floor of 75 Chambers.

3

NYC-WTC_000122165