

ASBESTOS INSPECTION REPORT

PAGE 1 OF 1

PREMISE NO. 97		STREET CHAMBERS STREET				INSPECTION DATE 8/2/02	
FLOOR Roof	ZIP 10007	BORO CODE 1	BLOCK	LOT	SQUAD # 1	BADGE # AD10	
INSPECTOR ALPHONSO PLUMPTRE		BLDG TYPE	BASIS OF INSPECT.			PHOTOS TAKEN YES / NO	
CONTRACTORS NAME FIBER CONTROL					SAMPLE NO.		
ADDRESS 3010 BURNS AVE					CITY WANTAGH		
STATE N.Y.					ZIP 11793		
PHONE (616) 781-3000					SAMPLE NO.		
LABORATORY NAME WARREN & PANZER ENGINEERS, PC					OWNERS NAME Dee & Dee of Chambers St		
ADDRESS 228 E. 45TH ST					CITY N.Y.		
STATE N.Y.					ZIP 10017		
PHONE (212) 922-0077					STATE N.Y.		
CONTACT PERSON:					TIME OF INSPECTION FROM: 12:15 am/pm TO: 1:00 am/pm		
INSPECTION DISCLOSED:							
The cleanup of the started in the early part of the day. Visual inspection was done on the roof after the cleanup and no visible debris on the roof.							

NOV #	INFRACTIONS	RESULT CODE
		5
NOV #		SUPERVISORS INITIALS
		<i>[Signature]</i>

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access 4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 30/93

FILE

WTC Visual Survey Form

Premise Address: <u>97 Chambers St</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>Debris on Elevator mechanical Roof - Roof has WTC debris on the lower end. There is also a lot of non-WTC sand type debris on roof</u>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments: <u>Construction work on all floors</u>					

Date: 5/14/2002Inspection Team: Name: CHAL

Agency: _____

Name: _____ Agency: _____

ENTERED

WTC Visual Survey Form

Premise Address: 97 Chambers Street

Block: Residential ☐ Commercial ☐ **Name of Building:** DEE & DEE

Lot: Mix Use ☒ Other ☐

of Stories: 5 **AKA's:**

Building Owner/Management: Telephone Number: (212) 243-5800

Name: DEE & DEE **FAX:** ()

Address: 30-100 St. Manhattan

On Site Contact: Telephone Number: (212) 233-3880

Name: GREASY KAROLCA - MEN

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☒ No

Exterior Survey Performed ☐ Yes ☒ No

General Clean Up ☒ Yes ☐ No **Locations:** Exterior Stairs - 4th

ACM Clean Up ☐ Yes ☒ No **Locations:**

Air Monitoring ☐ Yes ☒ No **Locations:**

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

	Inspected	Debris
North ☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East ☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West ☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Facade Description: Broken windows etc.

Roof

Debris: ☐ No Visible /Fine Layer ☒ 1/2 to 1" ☐ > 1"

Description: Light dust
South side brick head wall - some roof domes (Pneumatic)

Setbacks N/A ☐

Floor:	Debris:
Floor: _____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Comments: Roof debris in needs to be tested.

Date: 1/13/2002

Inspection Team: Name: R. Fitzpatrick

Agency: US EPA

Name: R. K. [unclear]

Agency: DEE & DEE