

WTC Visual Survey Form

Premise Address: <u>97 Chambers Street</u>		
Block: <u>149</u>	Residential ☐ Commercial ☐ Mix Use ☒ Other ☐	Name of Building: <u>DEE & DEE</u>
Lot: <u>12</u>		
# of Stories: <u>5</u>	AKA's: <u>79-81 Reade St</u>	
Building Owner/Management: Name: <u>DEE & DEE</u>		Telephone Number: (212) <u>243-5800</u> FAX: () <u> </u>
Address: <u>30-142 St Manhattan</u>		
On Site Contact: Name: <u>Gregory Laroche - MGR</u> Telephone Number: (212) <u>233-3830</u>		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☒ No		
Exterior Survey Performed ☐ Yes ☒ No		
General Clean Up ☒ Yes ☐ No		Locations: <u>Exterior Clean-up</u>
ACM Clean Up ☐ Yes ☒ No		Locations: <u> </u>
Air Monitoring ☐ Yes ☒ No		Locations: <u> </u>
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Broken windows etc

Roof

Debris: ☐ No Visible /Fine Layer light dust ☒ ½ to 1" of dust ☐ > 1" of dustDescription: South side back hand wall - New roof domes (Pneumatic roof)Setbacks N/A ☐

Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Roof debris is going to be tested.Date: 1/13/2002Inspection Team: Name: R. FitzpatrickAgency: US EPAName: R. FitzpatrickAgency: NYC DEP