

WTC Visual Survey Form

Premise Address: <u>75 Chambers St</u>		
Block: Lot:	Residential ☒ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
# of Stories: <u>86</u>	AKA's:	
Building Owner/Management: Name: <u>Madison Co</u>		Telephone Number: (212) <u>233-5658</u> FAX: ()
Address: <u>277 Broadway, 6th Floor</u>		
On Site Contact: Name: <u>Ali Haxhija - Super</u> Telephone Number: (212) <u>233-5658</u>		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☒ No		
Exterior Survey Performed ☐ Yes ☒ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☐ Yes ☒ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:		
North ☒ N/A	Inspected ☐ Yes ☐ No	Debris ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East ☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West ☒ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Facade Description: <u>Smear windows etc</u>		
Roof		
Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" <u>light dust</u> ☐ > 1" <u>1 dust.</u>		
Description: _____		
Setbacks N/A ☐		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Comments		

Date: 1/24/2002

Inspection Team: Name: R. Fitzpatrick
Name: K. Raimondo

Agency: US EPA
Agency: NYC DEP