?

WTC Visual Survey Form

Premise Address: 79 Chambers St.

Block: **Lot:**	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐ _____	**Name of Building:** The 79 Company
# of Stories: 5	**AKA's:**	

Building Owner/Management:
Name: The 79 Company — Telephone Number: (212) 233-5655
Address: 277 Broadway, 6th Floor — FAX: ( )

On Site Contact:
Name: ALI HAKHIJA - Super — Telephone Number: (212) 233-5655

Building Owner Management Activities

Interior Survey Performed	☐ Yes	☒ No	
Exterior Survey Performed	☐ Yes	☒ No	
General Clean Up	☒ Yes	☐ No	Locations: _____
ACM Clean Up	☐ Yes	☐ No	Locations: _____
Air Monitoring	☐ Yes	☒ No	Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: Brick windows etc

Roof

Debris: ☒ No Visible /Fine Layer (light dust) ☐ ½ to 1" (dust) ☐ > 1" (dust)
Description: _____

Setbacks N/A ☒

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/24/2002 — Inspection Team: Name: R. Fitzpatrick Agency: U.S. EPA
Name: E. Rammana Agency: NYC DEP

34