

WTC Visual Survey Form

Premise Address: <u>277 Broadway</u>		
Block: Lot:	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building: <u>Chambers Company</u>
# of Stories: <u>15</u>	AKA's:	
Building Owner/Management: Name: <u>Chambers Company</u>		Telephone Number: <u>(212) 233-5688</u> FAX: ()
Address: <u>Same</u>		
On Site Contact: Name: <u>ALI HAKHIA - Super</u>		Telephone Number: <u>(212) 233-5688</u>
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☒ No		
Exterior Survey Performed ☐ Yes ☒ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☐ Yes ☒ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:		
North ☒ N/A	Inspected ☐ Yes ☐ No	Debris ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West ☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Facade Description: <u>Smaller windows etc.</u>		
Roof		
Debris: ☒ No Visible/Fine Layer ^{light dust} ☐ 1/2 to 1" of dust ☐ > 1" of dust.		
Description: _____		
Setbacks <u>N/A</u> ☒		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Comments <u>Ledges below roof clean.</u>		

Date: 1/24/2002

Inspection Team: Name: B.F. Fitzpatrick
Name: R. Lammiman

Agency: US EPA
Agency: NIC DEP