

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**

**JOEL A. MIELE, SR., P.E.
COMMISSIONER**

**ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____ Date Sampled: 2/23/02
Premise: 175 BROADWAY Time: 1130 am/pm
Boro: MAN.
Inspector: Luisa N. Reyna Luisa N. Reyna
Print Sign

TURNAROUND TIME: 24HRS [☒] 48HRS [] 1 WK [] 2 WKS [] 4 WKS []

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A055028	Fibrous debris	North parapet wall roof	
2. 20223/A055029	Fibrous debris	South parapet wall roof	
3. 20223/A055030	Fibrous debris	North parapet wall roof	
4. 20223/A055031	Fibrous debris	South side floor on roof	
5. 20223/A055032	Fibrous debris	North west parapet wall roof	
6. 20223/A055033	Fibrous debris	North west parapet wall roof	
7. 20223/A055034	Fibrous debris	N.W. parapet wall roof	
8. 20223/A055035	Fibrous debris	N.W. parapet wall roof	
9. 20223/A055036	Fibrous debris	metal stairs west side roof	
10.			

ANALYSES REQUESTED: Asbestos PLM [] Asbestos TEM [] Lead []

DATE	TIME	ACCEPTED BY	COMMENTS
2/23/02	3:55 P	PRINT Greg Frightner	SQA Cust 97 BEC C96
		SIGN <u>[Signature]</u>	
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

DEP ACP REV 5/96

BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

JOEL A. MIELE, SR., P.E.
 COMMISSIONER

DUPLICATE

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: _____ Date Sampled: 2/23/02
 Premise: 175 BROADWAY Time: 1130 am/pm
 Boro: MAN.
 Inspector: Luisa N. Reyna Luisa N. Reyna
 Print Sign

TURNAROUND TIME: 24HRS [X] 48HRS [] 1 WK [] 2 WKS [] 4 WKS []

	SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
CH 1-7	1. 20223/A055028	Fibrous debris	North parapet wall roof	050
(-)	2. 20223/A055029	Fibrous debris	South parapet wall roof	051
	3. 20223/A055030	Fibrous debris	North parapet wall roof	052
	4. 20223/A055031	Fibrous debris	South side floor on roof	053
	5. 20223/A055032	Fibrous debris	North west parapet wall roof	054
	6. 20223/A055033	Fibrous debris	North west parapet wall roof	055
	7. 20223/A055034	Fibrous debris	N.W. parapet wall roof	056
(-)	8. 20223/A055035	Fibrous debris	N.W. parapet wall roof	057
	9. 20223/A055036	Fibrous debris	metal stairs west side roof	058
	10.			

ANALYSES REQUESTED: Asbestos PLM [] Asbestos TEM [] Lead []

DATE	TIME	ACCEPTED BY	COMMENTS
2/23/02	3:55 P	PRINT Greg F. [Signature] SIGN [Signature]	Sqft Cst 94 BEC C96
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

DEP ACP REV 5/96