

WTC Visual Survey Form

Premise Address: 176 Broadway		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: 15	AKA's:	
Building Owner/Management:		Telephone Number: (212) 370-1480
Name: John J. Gregory		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North ☐ N/A South ☐ N/A East ☐ N/A West ☐ N/A	Inspected ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		Debris ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
	Facade Description:				
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Comments					
Super said that the gravel had been removed from the roof. However, there are many pockets of WTC debris on roof					

Date: 3/23/2002 **ENTERED** Inspection Team: Name: CARL Agency: _____
Name: _____ Agency: _____