

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**

**JOEL A. MIELE, SR., P.E.
COMMISSIONER**

**ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____ Date Sampled: 2/23/02
Premise: 177 Broadway Time: 10:30 am/pm
Boro: Man.
Inspector: L. Reyna Larry Reyna
Print Sign

TURNAROUND TIME: 24HRS [☒] 48HRS [☐] 1 WK [☐] 2 WKS [☐] 4 WKS [☐]

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1.20223/A055019	fibrous debris	east parapet wall roof	
2.20223/A055020	fibrous debris	east parapet wall roof	
3.20223/A055021	fibrous debris	flom south wall roof	
4.20223/A055022	fibrous debris	Mid south flom roof	
5.20223/A055023	fibrous debris	north parapet wall roof	
6.20223/A055024	fibrous debris	flom water tank roof	
7.20223/A055025	fibrous debris	South wall parapet roof	
8.20223/A055026	fibrous debris	swimming pool parapet wall roof	
9.20223/A055027	fibrous debris	West parapet wall roof	
10.			

ANALYSES REQUESTED: Asbestos PLM [☐] Asbestos TEM [☐] Lead [☐]

DATE	TIME	ACCEPTED BY	COMMENTS
2/23/02	3:55 P	PRINT Greg Frychman	Safe cust at BEC 696
		SIGN My JTE	
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

DEF ACP REV 9/96

DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

JOEL A. MIELE, SR., P.E.
COMMISSIONER

DUPLICATE

POSITIVE

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: _____ Date Sampled: 2/23/02
Premise: 177 Broadway Time: 10:30 AM/PM
Boro: Man.
Inspector: L. Reyna L. Reyna
Print Sign
TURNAROUND TIME: 24HRS ☒ 48HRS ☐ 1 WK ☐ 2 WKS ☐ 4 WKS ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
CHRY 1.5 1. 20223/A055019	Fibrous debris	East parapet wall roof	041
2. 20223/A055020	Fibrous debris	East parapet wall roof	042
3. 20223/A055021	Fibrous debris	South wall roof	043
4. 20223/A055022	Fibrous debris	Mid south floor roof	044
5. 20223/A055023	Fibrous debris	North parapet wall roof	045
6. 20223/A055024	Fibrous debris	Long water tank roof	046
7. 20223/A055025	Fibrous debris	South wall parapet roof	047
8. 20223/A055026	Fibrous debris	Swimming pool parapet wall roof	048
CHRY 1.5 9. 20223/A055027	Fibrous debris	West parapet wall roof	049
10.			

ANALYSES REQUESTED: Asbestos PLM ☐ Asbestos TEM ☐ Lead ☐

DATE	TIME	ACCEPTED BY	COMMENTS
2/23/02	3:55 P	PRINT Greg Frachina SIGN <u>Greg Frachina</u>	Safe cost at BEC Lab
		P	
		S	
		P	
		S	
		P	
		S	

DEP ACP REV 5/96