

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**

**JOEL A. MIELE, SR., P.E.
COMMISSIONER**

**ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____ Date Sampled: 2/23/02
Premise: 179 Broadway Time: 11:00 am/pm
Boro: Mn
Inspector: Luisa M. Reyna Luisa M. Reyna
Print Sign
TURNAROUND TIME: 24HRS ☒ 48HRS ☐ 1 WK ☐ 2 WKS ☐ 4 WKS ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A055010	Fibrous debris	Front East parapet roof	
2. 20223/A055011	Fibrous debris	by Chimney roof	
3. 20223/A055012	Fibrous debris	Roof middle flnk	
4. 20223/A055013	Fibrous debris	Roof parapet wall	
5. 20223/A055014	Fibrous debris	by roof electrical switches	
6. 20223/A055015	Fibrous debris	by electrical conduits on roof	
7. 20223/A055016	Fibrous debris	by A/C on roof	
8. 20223/A055017	Fibrous debris	by roof ledge	
9. 20223/A055018	Fibrous debris	West parapet wall/roof	
10.			

ANALYSES REQUESTED: Asbestos PLM ☐ Asbestos TEM ☐ Lead ☐

DATE	TIME	ACCEPTED BY	COMMENTS
2/23/02	3:55	PRINT Greg Frightman	SFE Cost 91 BEC Lab
		SIGN <u>RE</u> <u>RE</u>	
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

DEP ACP REV 5/96

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368**

**JOEL A. MIELE, SR., P.E.
COMMISSIONER**

DUPLICATE

**ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____ Date Sampled: 2/23/02
Premise: 179 Broadway Time: 11:00 am/pm
Boro: Mn
Inspector: Luisa M. Reyna Luisa M. Reyna
Print Sign
TURNAROUND TIME: 24HRS [☒] 48HRS [] 1 WK [] 2 WKS [] 4 WKS []

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
CH 4.7 1. 20223/A055010	Fibrous debris	Front east parapet roof	032
2. 20223/A055011	Fibrous debris	by chimney roof	033
3. 20223/A055012	Fibrous debris	roof middle part	034
4. 20223/A055013	Fibrous debris	roof parapet wall	035
5. 20223/A055014	Fibrous debris	by roof electrical switch	036
CH 5.7 6. 20223/A055015	Fibrous debris	by electrical conduit on roof	037
7. 20223/A055016	Fibrous debris	by A/C on roof	038
8. 20223/A055017	Fibrous debris	by roof ledge	039
9. 20223/A055018	Fibrous debris	West parapet wall	040
10.			

ANALYSES REQUESTED: Asbestos PLM [] Asbestos TEM [] Lead []

DATE	TIME	ACCEPTED BY	COMMENTS
2/23/02	3:55	PRINT Greg Frightman SIGN <u>AE</u>	S&E Cust 91 BEC Lab
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

DEP ACP REV 9/96