

Asbestos Inspection Report

Premise No. 189 BROADWAY					Inspection Date: 11-26-02	
Floor ROOF & FACADE	Zip 10048	Borough 1	Block	Lot	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken Yes ☒ No ☐
Contractor's Name ACTION REMEDIATION INC./FIBER CONTROL				Sample Number N/A		
Address City 3010 BURNS AVENUE WANTAGH				Sample Number N/A		
State Zip Phone NY 11793 (516)781-3000				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: 0600 PM - 1200 MID		

TUESDAY NOVEMBER 26 2002

THE CLEAN UP OF THE ROOF AREA BENEATH THE A/C UNITS AND THE REMAINING PORTION OF THE NORTH FACADE WAS CONDUCTED. THE CLEAN UP OF THE EAST FACADE AND A PORTION OF THE NORTH FACADE HAD BEEN PERFORMED YESTERDAY. A PLASTIC DYKE WAS CONSTRUCTED TO COLLECT WATER RUN OFF. PLASTIC SHEETING WAS ALSO INSTALLED BEHIND THE METAL ROLL DOWN GATE OF THE "STYLZ" CLOTHING STORE. A GAP EXISTS BETWEEN THE FACADE SIGN AND THE ROLL DOWN GATE. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP PROJECT WAS PERFORMED BY JOHN BURGESS (CERTIFICATE # AH 97-11398 EXP 09/03) OF WARREN & PANZER ENGINEERS. AIR SAMPLING EQUIPMENT WAS SET UP ON THE STREET AND SIDEWALK JUST BEYOND THE PLASTIC DYKE. ALL FACADE SURFACES WERE THOROUGHLY HEPA-VACUUMED AND THEN POWER WASHED WITH A LOW PRESSURE SPRAY. AT THE CONCLUSION OF CLEAN UP ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES AND I OBSERVED NO VISIBLE WTC DEBRIS. THE CONTRACTOR WILL BE ON SITE EARLY IN THE MORNING TO REMOVE THE PLASTIC SHEETING INSTALLED BEHIND THE METAL ROLL DOWN GATE AND TO PERFORM ANY MINOR CLEANING OF STORE FRONT WINDOWS THAT MAY HAVE RESIDUAL DEBRIS FROM WATER SEEPAGE.

WEDNESDAY NOVEMBER 27 2002

THE PLASTIC SHEETING INSTALLED BEHIND THE METAL ROLL DOWN GATE OF THE "STYLZ" CLOTHING STORE IS REMOVED. MINOR RECLEANING OF THE INSIDE PORTION (BACK) OF THE GATE IS PERFORMED. THE CLEAN UP PROJECT AT THE PREMISE IS NOW COMPLETE.

R