

WTC Visual Survey Form

Premise Address: 11 JOHN AKA 192 BROADWAY		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: 8	AKA's:	
Building Owner/Management: COLLEGIATE CHURCH		Telephone Number: (212) 233-1960
Name: DAVID RIVNAR		FAX: ()
Address: 45 JOHN STREET NEW YORK NY 10038		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
North	☐ N/A	Inspected	Debris
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Facade Description: _____ _____			
Roof			
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"			
Description: _____ _____			
Setbacks N/A ☒			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments			
SOME MATERIAL WAS OBSERVED EMBEDDED IN THE CORNICE			
OF THE SOUTH FACADE AND ON A DORMER FRONT.			
_____ _____ _____			

Date: 07/03/2002

Inspection Team: Name: DA / A020

Agency: DEP

Name: _____

Agency: _____

Premise No. 11 JOHN STREET					Inspection Date: 08-11-02	
Floor FACADE	Zip 10038	Borough 1	Block 79	Lot 15	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken ☒ Yes / ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: 7 ⁰⁰ AM - 10 ³⁰ PM		
SUNDAY AUGUST 11, 2002						
THE CLEAN UP OF THE SOUTH FACADE OF THE PREMISE WAS CONDUCTED TODAY. THE CLEAN UP OF SOUTH FACADE OF 15 JOHN STREET OCCURRED SIMULTANEOUSLY. FOR THE PURPOSES OF AIR MONITORING, THE SOUTH FACADES OF THESE BUILDINGS WERE TREATED AS ONE WORK AREA. FIVE AIR SAMPLES WERE RUN ON THE OPPOSITE SIDE WALK (2 JOHN STREET). AIR SAMPLING WAS PERFORMED BY CHETRAM RAMRAJ (CERTIFICATE # AH 98-19842 EXP 07/03) OF WARREN & PANZER ENGINEERS. AFTER CLEANING ACTIVITIES CEASED, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES OF 11 JOHN STREET, AND OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THIS PREMISE IS NOW COMPLETE.						

PPP