

WTC Visual Survey Form

1001219

Premise Address: 196 Broadway	
Block: 79	Residential ☐ Commercial ☒
Lot: 16	Mix Use ☐ Other ☐
# of Stories:	AKA's: TGI
Building Owner/Management:	
Name:	Telephone Number: ()
Address:	
On Site Contact:	
Name: Juan	Telephone Number: ()
Building Owner Management Activities	
Interior Survey Performed ☐ Yes ☐ No	
Exterior Survey Performed ☐ Yes ☐ No	
General Clean Up ☐ Yes ☐ No	Locations: _____
ACM Clean Up ☐ Yes ☐ No	Locations: _____
Air Monitoring ☐ Yes ☐ No	Locations: _____
Copies of All Reports and Data Requested ☐ Yes	

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☒ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Roof

Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"Description: At Rear portion of Roof
Scattered debris at about the center of RoofSetbacks N/A ☒

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Heavy debris at back
of Building

Date: 4/30/2002

Inspection Team: Name: CAR

Agency: _____

Name: _____

Agency: _____

ENTERED
4/30 R10

Asbestos Inspection Report

Premise No. 196 BROADWAY					Inspection Date: AS NOTED	
Floor ROOF AND FACADES	Zip 10038	Borough 1	Block 79	Lot 16	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken ☒ Yes ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from:		
<u>SUNDAY AUGUST 11 2002 (8⁰⁰AM - 8⁰⁰PM)</u> <u>CLEAN UP ACTIVITIES BEGIN ON THE ROOF OF THE PREMISE. A REMOTE DECONTAMINATION UNIT IS SET UP ONE LEVEL BELOW THE ROOF WORK AREA. AIR MONITORING FOR THIS PORTION OF THE WORK IS PERFORMED BY DIPO GLEMO (CERTIFICATE # AH 01-14694 EXP 03/03) OF WARREN & PANZER ENGINEERS.</u>						
<u>MONDAY AUGUST 12 2002 (8⁰⁰AM - 8⁰⁰PM)</u> <u>CLEAN UP ACTIVITIES ARE COMPLETED ON THE ROOF OF THE PREMISE. I CONDUCT A VISUAL INSPECTION OF THE CLEANED ROOF SURFACES AND OBSERVE NO VISIBLE WTC DEBRIS. THE CLEAN UP OF THE SET BACK AREA IS BEGUN TODAY. AIR MONITORING FOR THIS PORTION OF THE PROJECT IS PERFORMED BY FESY OSEMWEGIE (CERTIFICATE # AH 01-01030 EXP 01/03) OF WARREN & PANZER ENGINEERS.</u>						
<u>TUESDAY AUGUST 13 2002 TO THURSDAY AUGUST 15 2002 (8⁰⁰AM - 8⁰⁰PM)</u> <u>CLEAN UP ACTIVITIES CONTINUE ON THE SET BACK AS PER THE APPROVED SCOPE OF WORK.</u>						
<u>FRIDAY AUGUST 16 2002</u> <u>THE CLEAN UP OF THE SET BACK IS COMPLETED. I CONDUCT A VISUAL INSPECTION OF THE CLEANED SURFACES AND OBSERVE NO VISIBLE WTC DEBRIS.</u>						
<u>SUNDAY AUGUST 18 2002 (5⁰⁰AM - 12⁰⁰NOON)</u> <u>THE CLEAN UP PROJECT ON THE FACADE (BROADWAY) WAS CONDUCTED TODAY. A PLASTIC DYKE WAS CONSTRUCTED TO COLLECT RUN OFF WATER. A MOBILE DECON TRUCK WAS UTILIZED. AIR MONITORING FOR THIS PORTION OF THE WORK WAS CONDUCTED BY FESY OSEMWEGIE OF WARREN & PANZER. I CONDUCTED A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES AND OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT IS NOW COMPLETE.</u>						

RP