

Asbestos Inspection Report

Premise No. 202 BROADWAY					Inspection Date: AS NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 79	Lot 19	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken (Yes/No)
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		
MONDAY AUGUST 5, 2002 (8:00AM - 8:00PM) THE CLEAN-UP OF THE ROOF OF THE PREMISE BEGAN TODAY. A REMOTE DECONTAMINATION UNIT FOR THIS WORK WAS ERECTED ON THE ROOF OF THE ADJACENT BUILDING (204 BROADWAY). FIVE AIR SAMPLES WERE RUN FOR THE DURATION OF TODAY'S ACTIVITIES ON THE ROOF OF THE ADJACENT BUILDING (204 BROADWAY). AIR SAMPLING FOR THIS PROJECT WAS PERFORMED BY FESDY OSEMWEGIE OF WARREN AND PANZER ENGINEERS.						
TUESDAY AUGUST 6, 2002 THE CLEAN UP PROCEEDS AS PER THE APPROVED SCOPE OF WORK. AIR MONITORING WAS PERFORMED BY FESDY OSEMWEGIE OF WARREN & PANZER.						
WEDNESDAY AUGUST 7 2002 THE CLEAN UP OF THE ROOF IS COMPLETED. AFTER CLEANING ACTIVITIES CEASED, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP OF THE WEST (BROADWAY) FACADE IS SCHEDULED FOR SUNDAY AUGUST 18 2002.						
SUNDAY AUGUST 18 2002 (7:30AM - 8:30AM) THE CLEANUP OF THE FACADE OF THE PREMISE (MODELL'S PORTION) IS CONDUCTED. THE CLEAN UP OF THE FACADE OF 196 BROADWAY WAS CONDUCTED SIMULTANEOUSLY. AIR MONITORING FOR THIS PORTION OF THE WORK WAS PERFORMED BY FESDY OSEMWEGIE OF WARREN & PANZER. I CONDUCTED A VISUAL INSPECTION OF THE CLEANED FACADE SURFACES OF THE PREMISE AND OBSERVED NO VISIBLE WTC DEBRIS.						

PL

WTC Visual Survey Form

BN# 1001221

Premise Address: <u>202 Broadway</u>		
Block: <u>79</u>	Residential ☐ Commercial ☒	Name of Building:
Lot: <u>19</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
Facade Description: <u>Awnings have visible debris</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 2/15/2002Inspection by: Name: APAgency: DEP

Name: _____ Agency: _____