

WTC Visual Survey Form

Premise Address: 204 BROADWAY		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: 2	AKA's:	
Building Owner/Management:		Telephone Number: (212) 233-1960
Name: COLLEGIATE CHURCH		FAX: ()
Address: 45 JOHN STREET NEW YORK NY 10038		
On Site Contact:		
Name: DAVID RINNAR		Telephone Number: (212) 233-1960
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: <u>FACADE</u>		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	Debris	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
Facade Description: _____					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>WTC DEBRIS CONCENTRATED ON ROOF SURFACES BELOW A/C</u>					
<u>UNITS AND ON THEIR SUPPORTING FRAMES. SPOT DEBRIS ALSO PRESENT</u>					
<u>ON ROOF SURFACES</u>					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 08/05/2002Inspection Team: Name: DA/A020Agency: NYC DEP

Name: _____ Agency: _____

E N Y T E R R E S