






WTC Visual Survey Form

Premise Address: <u>233 Broadway</u>		
Block: <u>123</u>	Residential ☐ Commercial ☒	Name of Building:
Lot: <u>22</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's: <u>2-20 Park Pl, 1-19 Barclay St</u>	
Building Owner/Management:		Telephone Number: ()
Name: <u>233 Broadway Owners LLC</u>		FAX: ()
Address: <u>220 E. 42nd St NYC 10017</u>		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☐ No		Locations: _____
Air Monitoring ☐ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1"					
Description: <u>Lower roof on Barclay St still have WTC material on it.</u>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 8/28/2002

Inspection Team: Name: AL

Name: _____

Agency: _____

Agency: _____

ENTERED

WTC Visual Survey Form

✓

Premise Address: 233 Broadway

Block: 123 **Residential** ☐ **Commercial** ☒ **Name of Building:** Woolworth
Lot: 22 **Mix Use** ☐ **Other** ☐

of Stories: 40 **AKA's:** 229 Bway

Building Owner/Management: **Telephone Number:** ()
Name: **FAX:** ()

Address:

On Site Contact: **Telephone Number:** (212)
Name: Mr. Suskin

Building Owner Management Activities
Interior Survey Performed ☐ Yes ☒ No
Exterior Survey Performed ☒ Yes ☐ No
General Clean Up ☒ Yes ☐ No **Locations:** Indoor
ACM Clean Up ☐ Yes ☒ No **Locations:**
Air Monitoring ☐ Yes ☒ No **Locations:**

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"

Facade Description: Never Cleaned

Roof

Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"

Description: Tiled Roof, Very Very Windy

Setbacks N/A ☐

Floor:	Debris:
29	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Comments

Date: 5/15/2002

Inspection Team: Name: CAPC

Agency:

Name:

Agency:

ENTERED