

WTC Visual Survey Form

1000029

Premise Address:

2 BROADWAY

Block: 11

Residential ☐Commercial ☐

Name of Building:

Lot: 1

Mix Use ☐Other ☐

of Stories: 34

AKA's:

Building Owner/Management:

Telephone Number: ()

Name:

FAX: ()

Address:

On Site Contact:

Name: Chris Lascaris, engr.

Telephone Number: ()

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ NoExterior Survey Performed ☐ Yes ☐ NoGeneral Clean Up ☐ Yes ☐ No Locations: _____ACM Clean Up ☐ Yes ☐ No Locations: _____Air Monitoring ☐ Yes ☐ No Locations: _____Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

North ☐ N/ASouth ☐ N/AEast ☐ N/AWest ☐ N/A

Inspected

☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☐ No☐ Yes ☐ No

Debris

☐ No Visible/Fine Layer☐ ½ to 1"☐ > 1"☐ No Visible/Fine Layer☐ ½ to 1"☐ > 1"☐ No Visible/Fine Layer☐ ½ to 1"☐ > 1"☐ No Visible/Fine Layer☐ ½ to 1"☐ > 1"

Facade Description:

Roof

35th

Debris:

☒ No Visible /Fine Layer☐ ½ to 1"☐ > 1"

Description:

gravel roof with suspect debris

Setbacks

N/A ☐Floor: 24th gravelDebris: ☒ No Visible/Fine Layer☒ ½ to 1"☐ > 1"Floor: 34th gravelDebris: ☒ No Visible/Fine Layer☒ ½ to 1"☐ > 1"Floor: 35th gravelDebris: ☐ No Visible/Fine Layer☐ ½ to 1"☐ > 1"Floor: 9th gravelDebris: ☒ No Visible/Fine Layer☒ ½ to 1"☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer☐ ½ to 1"☐ > 1"

Comments

Date: 2/02/2002

Inspection Team: Name:

RAMMOHAN

Agency: _____

Name: _____

Agency: _____